

Report ID: 25,649,850 Version: 6 29 Apr 2024 Created:

Make:	Subaru	Model:	Exiga	Body Style:	Wagon		Pass	Fail	N/A
Year:	2012	Registration:	QBS715	Reg Expiry:	05 Jan 2025	Engine			L
	13 May 2025	Odometer:	101,352 Kms	Good No:	25649850	Oil level	~		
VIN:	7AT0GF1RX23020745	Next Service:		Service Histor		Smoke & fumes	~		
			·			Performance	~		
	port is not a warranty	avation is made	for one and miles as	Danta hava nat	heen dispensied of	Noise	~		
diagnostic te	a guide only. Conside sting undertaken. The	vehicle has beer	n driven up to 50km/h	from cold. The	Vendor recommends	Cooling System			
a full mechar	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	S PT SC	-0	SW SD	-161-	s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc w			The	SW	Operation	~		
R = rust PT = paint def				$\prod$		Noise		~	
C = crack					S PT	Clutch		-	~
P = pin dent	HID				74114	CV joints	~		-
* = decals	S PT SC 916			The	ELD's	Wheel bearings	~		
SC = stone chips						Brakes			<u> </u>
W = significant scuffs S PT S P W S P W S P W S P W						Performance	~		
		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	-	of tyre	<u> </u>
								mm	
						Right front		.0	mm
						Left rear		.0	mm
Condition	as During Pody Inc	naction				Right rear		.0	 mm
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		L
						Operation	~		
Interior Comments						Electrical / Accessories			<u> </u>
Seats	Drivers Sea	at Torn				Head lights	~		
	Cood					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	1					Window winder FR	~		
General (	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	· •		
			Dry			Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera	~		
L	-								<u> </u>
Inspected by: Samuel Weir Date: 22 Mar 2024									
I have read and understood this condition guide. Name:									