

Basic Vehicle Condition Guide

Report ID: 25,653,946


Version: 3

Created: 15 Apr 2024

Make: Model: Toyota Hilux **Body Style:** Utility Year: 2020 Registration: MRR89 Reg Expiry: 19 May 2024 WoF Expiry: **Odometer: Good No:** 22 Apr 2025 72,178 Kms 25653946 VIN: MR0JA3DD600346538 Next Service: 87161 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | |
|--------------------------|---------|--|--|
| Seats | Average | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Average | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Lukin Koveskali Inspected by: Date:

Name:

| | Pass | Fail | N/A | |
|--|---------------------------------------|------|-----|--|
| Engine | | 1 | | |
| Oil level | ~ | | | |
| Smoke & fumes | \(\times \) | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | ~ | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | | | ~ | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread depth of tyres) | | | | |
| Left front 3.0 mm | | | | |
| Right front | 3.0 | | mm | |
| Left rear | 3 | .0 | mm | |
| Right rear | 3 | .0 | mm | |
| Spare Yes | | | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | ~ | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | | |
| Window winder FL | <i>V</i> | | | |
| Window winder FR | ~ | | | |
| Window winder RL | ~ | | | |
| Window winder RR | | | | |
| Rear view mirrors | V | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 2 | • | • | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | ~ | | | |
| | | • | • | |

26 Mar 2024

Signature: