

Report ID: 25,654,665 Version: 1 Created: 28 Mar 2024

Make:	Ford	Model:	Mondeo	Body Style:	Wagon		Pass	Fail	N/A
Year:	2014	<b>Registration:</b>	HSQ750	<b>Reg Expiry:</b>	18 Jul 2024	Engine			
WoF Expiry:	19 Apr 2024	Odometer:	135,215 Kms	Good No:	25654665	Oil level	~		
VIN:	WF0GXXGBBGEB8685	Next Service:	148,000 Kms	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition 🖌			
	[ w					Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch D = dent R = rust PT = paint defect C = crack P = pin dent						Transmission			
						Operation		~	
						Noise	~		
						Clutch			~
						CV joints	~		
* = decals						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W P P P						Performance			
Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	-	of tvre	L 25)
Small stone chips in front windscreen						Left front			mm
						Right front			mm
						Left rear			mm
Conditions During Rody Inspection: Wet						Right rear	6.3 6.4		mm
Conditions During Body Inspection: Wet Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
						Suspension			
	-	ŀ				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
						Operation	~		
Interior Comments						Electrical / Accessories	V		
Seats		Stains otherwise good				Head lights			
Seals						Tail lights	~ ~		
Carpets	Average								
	Good					~			
Panels					Dashboard warning lights	~			
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
General (	Comments					Window winder FR	~		
Service oil warning on speedo						Window winder RL	~		
Possible issue with transmission, advise to have checked. Hesitant on take off, jolting and over revving						Window winder RR	~		
during gea	r changes					Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		1
Road Con	ditions During Tes	t Drive:	Wet			Central locking	~		<u> </u>
Engine Timing Mechanism: Cambelt						Remote locking	~		<u> </u>
Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~
LYNGENCE	or carri bert nepide	cincili. p	NU	11113.		Reversing camera			~
Inspected by: Hoani Saunders Date: 27 Mar 2024									
I have read	and understood th	is condition c	uide. Name:			Signature:			