

Basic Vehicle Condition Guide

Report ID: 25,656,861


Version: 1

Created: 03 Apr 2024

Make: Model: Holden Trax **Body Style:** SUV Year: 2018 Registration: LUH832 Reg Expiry: 25 Feb 2025 WoF Expiry: **Odometer:** 06 Mar 2025 67,901 Kms **Good No:** 25656861 VIN: KL3BA7689JB716063 Next Service: 77,000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Bonnet guard broken. Stone chips in front screen

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Tested battery and passed. Partial belly pans. Runs on 95 octane fuel

<u>Interior Comments</u>		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Good	

General Comments

Air conditioning and heating work fine at inspection time

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

25 Mar 2024 Inspected by: Gary Adams Date:

Name:

Pass	Fail	N/A
~		
~		
~		
~		
~		
~		
~		
~		
~		
		~
~		
~		
~		
~		
depth	of tyre	es)
7	.0	mm
7	.0	mm
7.0		mm
7.0		mm
	Yes	
•		
~		
~		
~		
~		
~		
~		
V		
\(\triangle \)		
V V V		
\(\times \) \(\t		
\(\times \) \(\t		
V V V V V		
V V V V V		
V V V V V		
V V V V V V V V V		
-		·
-		V
<i>V</i>		V
<i>V</i>		· ·
<i>V</i>		V
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ

Signature: