# Turners

# Basic Vehicle Condition Guide

Report ID: 25,660,180
Version: 3
Created: 17 May 2024

| | | |
|---|---|---|
| **Make:** Mazda | **Model:** CX-8 | **Body Style:** SUV |
| **Year:** 2020 | **Registration:** MTA849 | **Reg Expiry:** 19 Sep 2024 |
| **WoF Expiry:** 19 Mar 2025 | **Odometer:** 78,135 Kms | **Good No:** 25660180 |
| **VIN:** JM0KG4W2A0020201! | **Next Service:** 87000 kms | **Service History:** No |

**Note: This report is not a warranty**
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**
S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs



Note: some defects & blemishes may not be displayed in the diagram

## Body Inspection Comments

**Conditions During Body Inspection:** Dry

## Under Carriage & Under Bonnet Inspection Comments

4WD

## Interior Comments

| Seats | Good |
|---|---|
| Carpets | Good |
| Panels | Good |
| Dashboard | Good |

## General Comments

W/S stone chip in CVA. (Repaired, Certificate of repair in vehicle)
Key battery low warning on dash.
A/C cold: 9c, hot: 36c, AMB: 16c.

**Road Conditions During Test Drive:** Dry

**Engine Timing Mechanism:** Timing Chain

**Evidence of Cam Belt Replacement:** Not Applicable  **Kms:**

| | Pass | Fail | N/A |
|---|:---:|:---:|:---:|
| **Engine** | | | |
| Oil level | ✔ | | |
| Smoke & fumes | ✔ | | |
| Performance | ✔ | | |
| Noise | ✔ | | |
| **Cooling System** | | | |
| Coolant condition | ✔ | | |
| Performance | ✔ | | |
| Radiator / Hoses (visual) | ✔ | | |
| **Transmission** | | | |
| Operation | ✔ | | |
| Noise | ✔ | | |
| Clutch | | | ✔ |
| CV joints | ✔ | | |
| Wheel bearings | ✔ | | |
| **Brakes** | | | |
| Performance | ✔ | | |
| Hand Brake | ✔ | | |
| **Tyres** (lowest observed tread depth of tyres) | | | |
| Left front | 6.0 | | mm |
| Right front | 6.0 | | mm |
| Left rear | 5.0 | | mm |
| Right rear | 5.0 | | mm |
| Spare | Yes | | |
| **Suspension** | | | |
| Suspension performance | ✔ | | |
| Steering performance | ✔ | | |
| Shock absorbers | ✔ | | |
| **Air Conditioning / Heater** | | | |
| Operation | ✔ | | |
| **Electrical / Accessories** | | | |
| Head lights | ✔ | | |
| Tail lights | ✔ | | |
| Indicators | ✔ | | |
| Dashboard warning lights | ✔ | | |
| Wipers (front & rear) | ✔ | | |
| Window winder FL | ✔ | | |
| Window winder FR | ✔ | | |
| Window winder RL | ✔ | | |
| Window winder RR | ✔ | | |
| Rear view mirrors | ✔ | | |
| Radio (basic test only) | ✔ | | |
| CD (basic test only) | | | ✔ |
| Number of keys | 2 | | |
| Central locking | ✔ | | |
| Remote locking | ✔ | | |
| Sat. Nav. (basic test only) | ✔ | | |
| Reversing camera | ✔ | | |

**Inspected by:** Eleoit Kumar

**Date:** 03 Apr 2024

I have read and understood this condition guide. Name: ........................................ Signature: ........................................