

Report ID: 25,669,873 Version: 2 04 Apr 2024 Created:

Make:	Audi	Model:	A3	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2005		JAQ150	Reg Expiry:	22 May 2024	Engine			
	01 Dec 2024	Odometer:	139,548 Kms	Good No:	25669873	Oil level	~		
VIN:	WAUZZZ8P35A16564	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
		_				Performance	~		
Key:	sc	-0	SP SP		s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent						Operation	~		
						Noise	~		
PT = paint defect C = crack						Clutch	V		
P = pin dent	Ho				JUII —	CV joints			~
* = decals	sc pp				Ell'As	, · · · · · · · · · · · · · · · · · · ·	~		
SC = stone chips						Wheel bearings	~		
W = significant scuffs W S S D P W S						Brakes			
						Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Windscreen stone chip						Tyres (lowest observed tread	d depth	of tyre	es)
Underbody oxidation						Left front	4	1	mm
						Right front	4	1	mm
						Left rear	1	2	mm
Conditions During Body Inspection:						Right rear	2 m		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
	Shock absorbers	~							
						Air Conditioning / Heater	1		·
						Operation		~	
Interior Comments						Electrical / Accessories			
Seats	Poor					Head lights	~		
<u></u>	Poor					Tail lights	~		
Carpets						Indicators	~		
Panels	Poor					Dashboard warning lights	V		
						Wipers (front & rear)	~		
Dashboa	rd Poor					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	•	~	
Left rear window not working						Window winder RR	~	•	
	od lining hanging down oning not working					Rear view mirrors	~		
	ining not working					Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		L
						Central locking			
Koad Con	ditions During Test	t Drive:	Dry				v		
Engine Tir	ming Mechanism:	Cambelt	t			Remote locking	~		
Evidence of Cam Belt Replacement: Yes Kms: 136,146						Sat. Nav. (basic test only)			~
				1.115. 13		Reversing camera			~
Inspected by: Lukin Koveskali Date: 04 Apr 2024									

I have read and understood this condition guide.

Name:

Signature: