

Basic Vehicle Condition Guide

Report ID: 25,675,247


Version:

Created: 24 Apr 2024

Make: Model: Mitsubishi L300 **Body Style:** Van Year: 2010 Registration: FLA493 **Reg Expiry:** 16 Jul 2024 WoF Expiry: **Odometer:** 220,770 Kms **Good No:** 25675247 VIN: JMASNP04VAA800355 Next Service: no service history Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Lh side of vehicle has damage. Lh slider door damaged. Rust in roof gutters. Slider door window rubber poor fit. Rh indicator lense broken. Rh head light has cracks. Lh side light has hole

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

LHR tyre side wall damaged and wheel spacers

| <u>Interior Comments</u> | | | | |
|--------------------------|---------|--|--|--|
| Seats | Average | | | |
| Carpets | Average | | | |
| Panels | Average | | | |
| Dashboard | Average | | | |

General Comments

LHR tyre has a nail in it.. All Air vents on dash broken. Lh park light n/w. No tools. No Jack, vehicle not groomed.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

| Inspected by: | Reuben Harvey | Date: | 05 Apr 202 |
|---------------|---------------|-------|------------|
|---------------|---------------|-------|------------|

Name:

| | | • | |
|---|---|---------|----------|
| | Pass | Fail | N/A |
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | V V | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | • | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | ~ | | |
| CV joints | | | ~ |
| Wheel bearings | ~ | | |
| Brakes | | ı | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed treac | depth | of tyre | es) |
| Left front | 6 | .0 | mm |
| Right front | 5.5 | | mm |
| Left rear | 0.0 | | mm |
| Right rear | 2.5 mm | | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | V | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | 1 |
| Operation | | | ~ |
| Electrical / Accessories | | | 1 |
| Head lights | | ~ | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | VVV | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | | | ~ |
| Window winder RR | | | ~ |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | | | ~ |
| Number of keys | 2 | | |
| Central locking | ~ | | |
| | ~ | | - |
| Remote locking | | l | |
| Remote locking Sat. Nav. (basic test only) | | | 1 |
| Remote locking Sat. Nav. (basic test only) Reversing camera | | | V |

Signature: