

Report ID: 25,675,441 Version: 3 06 May 2024 Created:

Make:	Toyota	Model:	Landcruiser Prado	Body Style:	SUV		Pass	Fail	N/A
Year:	2007	Registration:	EGS49	Reg Expiry:	30 Dec 2024	Engine			
WoF Expiry:	20 May 2025	Odometer:	317,308 Kms	Good No:	25675441	Oil level	~		
VIN:	JTEBU25JX05103497	Next Service:		Service Histor	y: Yes	Smoke & fumes	~		
			- ,			Performance	~		
	port is not a warranty		6 1 1			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:		-0	L SC			Radiator / Hoses (visual)	~		┼───
S = scratch	Ste	20			X	Transmission	V		
D = dent	P SC			1 - L	ED PT P SC	Operation	~		T
R = rust				10	7HIX	Noise	~		<u> </u>
PT = paint defe C = crack	ect III			+	SC	Clutch	~		<u> </u>
P = pin dent	LHC	KI		-	JIII —				~
* = decals	PT SC DI				ELA P	CV joints	~		<u> </u>
SC = stone chi	ps U			10		Wheel bearings	~		
W = significant scuffs SC S SC D						Brakes			<u> </u>
						Performance	~		<u> </u>
Body Insp	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		<u> </u>
						Tyres (lowest observed tread depth of tyres)			
						Left front	1.	.9	mm
						Right front	3.	.6	mm
						Left rear	3.1 m		mm
Conditions During Body Inspection: Dry						Right rear	3.4 m		mm
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
Under Ca	rriage & Under Boi	nnet inspectio	on Comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Commonte						Operation 🖌			
Interior Comments Front seat covers fitted Front seat covers fitted						Electrical / Accessories			
Seats	Front seat	covers fitted				Head lights	~		
Carpote	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Screw hol	es in centre cons	ole			Dashboard warning lights	<		
	, Good					Wipers (front & rear)	۲		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Tes	t Drive:	Dry			Central locking	~		
						Remote locking	~		1
Engine Tir	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Hoani Saunders Date: 18 Apr 2024									

I have read and understood this condition guide.

Name:

Signature: