

Basic Vehicle Condition Guide

Report ID: 25,676,035


Version: 2

09 May 2024 Created:

Make: Model: **BMW** X3 **Body Style:** Wagon Year: 2011 Registration: **PBY688 Reg Expiry:** 04 Jun 2024 WoF Expiry: **Odometer:** 22 Apr 2025 96,501 Kms **Good No:** 25676035 VIN: WBAWX520X0L39808 **Next Service:** 106400 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

4wd

Interior Comments				
Seats	Average			
Carpets	Average			
Panels	Average			
Dashboard	Average			

	_
General	Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Fail N/A Pass Engine Oil level Smoke & fumes 1 Performance V Noise / Cooling System Coolant condition Performance Radiator / Hoses (visual) **Transmission** Operation V Noise 1 Clutch 1 CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm 6.5 Right front 6.5 mm Left rear 5.5 mm Right rear 5.5 mm Spare N/A Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) 1 CD (basic test only) / Number of keys 2 Central locking Remote locking Sat. Nav. (basic test only) ~ Reversing camera

Uriah Pepene I have read and understood this condition guide.

lame:			

Signature:

18 Apr 2024

Date: