

Report ID: 25,676,625 Version: 1 09 Apr 2024 Created:

Make:	Mazda	Model:	Atenza	Body Style:	Sedan			Pass	Fail	N/A	
Year:	2009	Registration:	JLZ521	Reg Expiry:	02 Aug 2024	Eng	ine				
WoF Expiry:	12 Dec 2024	Odometer:	263,428 Kms	Good No:	25676625	Oi	llevel	~			
VIN:	7AT0C139X14102242	Next Service:	265000	Service Histor	y: No	Sn	noke & fumes	>			
						P e	rformance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or							bise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Cooling System				
							olant condition	~			
	SC W S		SC W SC W		SC W	Pe	rformance	~			
Key:	LISC W LIS			500-	JSC W	Ra	diator / Hoses (visual)	~			
S = scratch D = dent							nsmission			1	
D = dent R = rust	s sc w	1		710	ELL SC W] ot	peration	~			
PT = paint defe	ect NP	IT I			<u>17141</u>	No	bise	~			
C = crack					ww		utch			~	
P = pin dent	HE				7414	CV	/ joints	~			
* = decals	sc w 916				FID SC W] w	heel bearings	~			
SC = stone chips							Brakes				
W = significant scuffs SC W SC W P SC W P SC W							rformance	~			
Rodular	Position Commerts	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Ha	and Brake	~			
Body Inspection Comments A pillars chipped ,						Tyre	Tyres (lowest observed tread depth of tyres)				
A pinais chipped ,							Left front 5				
						Rio	ght front			mm	
							Left rear		5 m		
Condition	os During Body Ins	noction:	Dra			Rig	ght rear			mm	
Conditions During Body Inspection: Dry							Spare Yes				
Under Carriage & Under Bonnet Inspection Comments							Suspension				
	-						spension performance	~			
							eering performance	~			
							lock absorbers	~			
							Conditioning / Heater	•			
							Operation				
Interior Comments						Electrical / Accessories					
Seats							Head lights				
							il lights	~			
Carpets	Good						dicators	v v			
Danala	Good						ashboard warning lights	v v			
Panels							ipers (front & rear)	v v			
Dashboa	ard Good						indow winder FL	v v			
							indow winder FR	v v			
General (Comments						indow winder FR	v v			
Drives okay ,							indow winder RE	v v			
							ar view mirrors	v v			
							dio (basic test only)				
							D (basic test only)	ン ン			
						_	Number of keys 2				
Road Conditions During Test Drive: Dry							entral locking	v			
Engine Timing Mechanism: Timing Chain							mote locking	~			
Evidence of Cam Belt Replacement: Not Applicable Kms:							t. Nav. (basic test only)			~	
		ichichici [11113.		Re	eversing camera	~			
Inspected by: Donovan Matara Date: 09 Apr 2024											

I have read and understood this condition guide.

Name:

Signature: