

Report ID: 25,679,891 Version: 1 16 Apr 2024 Created:

Make:	Mitsubishi	Model:	Lancer	Body Style:	Sedan		Pass	Fail	N/A
Year:	2007	Registration:	HWZ588	Reg Expiry:	14 Apr 2024	Engine			
WoF Expiry:	16 Oct 2024	Odometer:	278,669 Kms	Good No:	25679891	Oil level		~	<u> </u>
VIN:	7AT0CJ0DX14001620	Next Service:	0	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		1
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		1
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		<u> </u>
	S SC W S	N	P SC W P SC	SC	w	Performance	~		<u> </u>
Key:	ISSCW IS	<u> </u>	PSCW PSC			Radiator / Hoses (visual)	~		<u> </u>
S = scratch D = dent						Transmission			<u> </u>
D = dent R = rust	SC DI	-		715	HIL SW	Operation	~		
PT = paint defe		FI		$\left(\left \right\rangle \right)$		Noise	~		
C = crack					PT SC W	Clutch	~		+
P = pin dent	110				세비	CV joints	~		
* = decals	S PT SC W PIE			-No-	S PT SC W	Wheel bearings	~		
SC = stone chips						Brakes	•		<u> </u>
W = significant scuffs P SC S W S C W S SC W S W PT SC W						Performance	~		1
Darle		Note: son	ne defects & blemishes	may not be disc	layed in the diagram	Hand Brake	~		+
Body Inspection Comments						Tyres (lowest observed tread	· ·	of tvre	L es)
Moisture inside LF headlight ,						Left front	3		
						Right front		, .5	mm
						Left rear			mm
Conditions During Body Inspection:						Right rear			mm
Conditions During Body Inspection: Dry					Spare		+ Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		+
						Shock absorbers	~		+
						Air Conditioning / Heater	•		L
						Operation		~	1
Interior Comments						Electrical / Accessories		•	<u> </u>
	Average					Head lights	~		T
Seats						Tail lights	v v		+
Carpets	Average						-		+
	Average						v		+
Panels						Dashboard warning lights	v		+
Dashboa	rd Average					Wipers (front & rear)	~		+
						Window winder FL	~		
General (omments					Window winder FR	~		
<u>General Comments</u> Drives okay ,needs a service ,					Window winder RL	~		+	
	,					Window winder RR	~		<u> </u>
						Rear view mirrors	~		──
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
						Number of keys	1		T
Road Con	ditions During Test	Drive:	Dry			Central locking	~		<u> </u>
Engine Ti	ming Mechanism	Cambel	+			Remote locking	~		<u> </u>
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~
Evidence	огсант вен керіас	ement. N	NO.	NITIS:		Reversing camera			~
Inspected by: Donovan Matara						Date: 16 Apr 2024			
inspected	= = y. = eneral matur	-							
I have read a	and understood th	is condition c	guide. Name: .			Signature:			