

Report ID: 25,681,373 Version: 1 24 Apr 2024 Created:

| Make: | Ford | Model: | Kuga | Body Style: | SUV | | Pass | Fail | N/A |
|--|--------------------------|-----------------|------------------------|--------------------|----------------------|-----------------------------|---|--------|-----|
| Year: | 2014 | Registration: | HKS446 | Reg Expiry: | 25 Aug 2024 | Engine | | | |
| WoF Expiry: | 29 Sep 2024 | Odometer: | 163,023 Kms | Good No: | 25681373 | Oil level | ~ | | |
| VIN: | WF0AXXWPMADK494 | Next Service: | 172,800 | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | aration is made | for ago and milaago | Darte have not | been dismonthed or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and th | nis can be arranged fo | or an additional o | harge. | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | SC S | <u>~</u> @ | P SC W P SC | | / SPW | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent R = rust PT = paint defect | | | | | | Operation | ~ | ~ | |
| | | | | | | Noise | ~ | | |
| C = crack | | | | | P SC | Clutch | | | ~ |
| P = pin dent | 110 | | | | 세비 | CV joints | ~ | | - |
| * = decals SC 919 SC W | | | | | | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs S W S W S P SC W S SC W S W P SC | | | | | | Performance | ~ | | |
| Dealerteen | <u></u> | Note: som | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | |
| Body Inspection Comments | | | | | | | Tyres (lowest observed tread depth of tyres | | |
| RH/F door trim bubblingg | | | | | | | | mm | |
| | | | | | | Right front | | 5 | mm |
| | | | | | | Left rear | | , 7 | mm |
| Conditions During Pody Inspection: Dry | | | | | | Right rear | 7 mm | | - |
| Conditions During Body Inspection: Dry | | | | | | Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| All wheel d | rive, | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | - | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Seats Good | | | | | Head lights | ~ | | |
| | Good | | | | | Tail lights | | ~ | |
| Carpets | Guou | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| | Card | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | ord Good | | | | | Window winder FL | ~ | | |
| | 1 | | | | | Window winder FR | ~ | | |
| General Comments | | | | | Window winder RL | ~ | | | |
| Moon roof cover not working, LH number plate light not working, | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 2 | I | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| | | | | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | ~ | | |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | ~ | | |
| L | | | | | | | I | 1 | |
| Inspecte | d by: Andre Richardso | on | | | | Date: 24 Apr 20 | 24 | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: