

Basic Vehicle Condition Guide

Report ID: 25,690,230


Version: 1

Created: 12 Apr 2024

Make: Model: Suzuki Swift **Body Style:** Hatchback Year: 2012 Registration: MYD828 Reg Expiry: 02 Jul 2024 **Odometer:** WoF Expiry: **Good No:** 22 Sep 2024 165,865 Kms 25690230 VIN: **Next Service:** JSAFZC32S00103354 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Crack in RF head light

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

No underbody inspection

<u>Interior Comments</u>		
Seats	wear, marks	
Carpets	Average	
Panels	Good	
Dashboard	missing knob on centre air vent	

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Melissa Wilson 12 Apr 2024 Inspected by: Date:

Name:

Pass	Fail	N/A
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
•	•	
~		
~		
depth	of tyre	es)
4.9		mm
5.3		mm
6.3		mm
6.6		mm
N/A		
•		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
1		•
1		
•		
~		
<i>'</i>		~
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	マ

Signature: