

Basic Vehicle Condition Guide

Report ID: 25,692,319


Version: 2

Created: 17 Apr 2024

Make: Model: Holden Barina **Body Style:** Hatchback Year: 2017 Registration: **KUZ114** Reg Expiry: 07 May 2024 WoF Expiry: **Odometer: Good No:** 30 Apr 2025 85,192 Kms 25692319 VIN: **Next Service:** KL3TA48E9JB000553 95000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Lukin Koveskali 15 Apr 2024 Inspected by: Date:

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	v v		
Performance	~		
Noise	'		
Cooling System			
Coolant condition	'		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	>		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front		5	mm
Right front		5	mm
Left rear	7	7	mm
Right rear	7		mm
Spare		Yes	
Suspension	•		
Suspension performance	~		
Steering performance	V V		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	V V V V V V		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)			~
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	~		

Signature: