

| Make: | Hyundai | Model: | Tucson | Body Style: | SUV | | Pass | Fail | N/A |
|--|---------------------------|----------------|----------------------|---------------------|-----------------------|--|--------|------|-----|
| Year: | 2017 | Registration: | QNK298 | Reg Expiry: | 07 Dec 2024 | Engine | | | |
| WoF Expiry: | 24 Nov 2024 | Odometer: | 76,187 Kms | Good No: | 25696034 | Oil level | ~ | | |
| VIN: | TMAJ3813MJJ516054 | Next Service: | 86,000km | Service Histor | y: Yes | Smoke & fumes | ~ | | |
| Notes This ve | | | | | | Performance | ~ | | |
| Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or | | | | | | Noise | ~ | | |
| diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechar | lical inspection prior to | purchase and t | his can be arranged | Tor an additional o | .narge. | Coolant condition | ~ | | |
| | S D | | SW | | S | Performance | V | | |
| Key: | | -(0) | | 5(0)- | | Radiator / Hoses (visual) | V | | |
| S = scratch D = dent | | | | | | Transmission | | | |
| R = rust | sw bla | | | 210 | HIL SW | Operation | ~ | | |
| PT = paint def | ect NP | IT I | | | 101h | Noise | ~ | | |
| C = crack | | | - | | S S | Clutch | | | ~ |
| P = pin dent | HE | | | | 2414 | CV joints | r | | |
| * = decals | - Alt | | | | ED S | Wheel bearings | V | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs W | | | | | | Performance | ~ | | |
| Dodulus | | Note: son | ne defects & blemish | nes may not be disp | blayed in the diagram | Hand Brake | ~ | | |
| Body Inspection Comments Windscreen stone chips | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| windscreen stone chips | | | | | | Left front 4 | | | mm |
| | | | | | | Right front | | 4 | mm |
| | | | | | | Left rear | | 3 | mm |
| Conditio | ns During Body Ins | nection: | Dry | | | Right rear | | 3 | mm |
| Conditions During Body Inspection: Dry | | | | | | Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | 105 | |
| Front wheel drive | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | · · | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | • | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | • | | |
| Seats | Good | | | | | Head lights | ~ | | |
| | | | | | | Tail lights | ~ | | |
| Carpets | Good | | | | | Indicators | ~ | | |
| Danala | Good | | | | | Dashboard warning lights | ~ | | |
| Panels | | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | ard Good | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FL Window winder FR | ~ | | |
| General (| Comments | | | | | Window winder FR Window winder RL | - | | |
| | | | | | | Window winder RL | レ レ | | |
| | | | | | | Rear view mirrors | - | | |
| | | | | | | | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | 2 | | ~ |
| | | | | | | Number of keys | 2 | | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| Engine Ti | ming Mechanism: | Timing | Chain | | | Remote locking | ~ | | |
| - | of Cam Belt Replac | - | lot Applicable | Kms: | | Sat. Nav. (basic test only) | | | ~ |
| | or cam beit nepide | ernent. p | | 11115. | | Reversing camera | ~ | | |
| Inspected by: Rowan Fey Date: 17 Apr 2024 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name: