

Report ID: 25,696,047 Version: 1 23 Apr 2024 Created:

Make:	BMW	Model:	3201	Body Style:	Wagon		Pass	Fail	N/A
Year:	2007	Registration:		Reg Expiry:	19 Apr 2024	Engine	I	l	1
WoF Expiry:		Odometer:	153,311 Kms	Good No:	25696047	Oil level	~		
VIN:	WBAVR720X0KW4216	Next Service:	Booked	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	wation is made	for one and miles as	Dauta hava nat	heen dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechani	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	SRSC	-0	SW SP		SP	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	S PT C SC			The	EID S	Operation	~		
R = rust				10	THIA	Noise	~		
PT = paint defe C = crack				+	S R SC	Clutch	•		~
P = pin dent	Ho					CV joints			~
* = decals	SDRSC 910			AL.	EIRs	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC S S P S T						Performance	~		
		Note: com	ne defects & blemishes			Hand Brake			
Body Insp	ection Comments	10000.3011	le delects & blemisnes	inay not be disp	layed in the diagram		<b>v</b>	ofturo	
Front Bumper Trim Broken						Tyres (lowest observed tread depth of tyres)			
						Left front	4		mm
						Right front		.5	mm
						Left rear	5.0		mm
Conditions During Body Inspection:						Right rear	5.5 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare N/A			
	mage & onder bon	ince inspectie	<u>in comments</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation		~	
Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
	Cood					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
Dashboa	iu .					Window winder FL	~		
						Window winder FR	~		
General Comments Luggage Cover Mounts Broken						Window winder RL	~		
Luggage Co	over mounts broken					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry Central locking									
			•			Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav									~
Evidence of	of Cam Belt Replace	ement: N	lot Applicable	Kms:		Reversing camera			~
·									
Inspected by: Samuel Weir Date: 22 Apr 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....