

Report ID: 25,699,172 Version: 3 24 Apr 2024 Created:

Make:	Honda	Model:	Accord	Body Style:	Sedan		Pass	Fail	N/A
Year:	2005	<b>Registration:</b>	CYC778	<b>Reg Expiry:</b>	18 Jun 2024	Engine	1	1	1
WoF Expiry:	19 Jul 2024	Odometer:	207,876 Kms	Good No:	25699172	Oil level	~		
VIN:	MRHCM66805P09120	Next Service:	180000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	Coolant condition		1
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			<u> </u>
D = dent	S PT SC W				S PT W	Operation	~		1
R = rust PT = paint def				r In	JHIH	Noise	~		
C = crack				+		Clutch			~
P = pin dent						CV joints	~		-
* = decals	sc w PIP			The	ET SPTW	Wheel bearings	~		
SC = stone chips						Brakes			<u> </u>
W = significant scuffs S W W W						Performance			1
Note: come defecte % blamiches may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed treat			
Minor stonechips front windscreen, both front headlights lenses dull,						Left front	· ·		
							_	3.7 mr	
						Right front		.5	mm mm
						Left rear		3.3	
Conditions During Body Inspection: Dry						Right rear	5	5.5 m	
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Possible split steering rack/control arm boot LHS grease splatter evident						Suspension			1
Possible spi	int steering rack/control	arm boot LHS gr	rease splatter evident			Suspension performance	~		
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
InteriorC	Average					Electrical / Accessories		1	
Seats	Average					Head lights		~	
Carpets	Average					Tail lights		~	
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		
Dashbud						Window winder FL	~		
- · ·						Window winder FR	~		
General Comments					Window winder RL	~			
LHF headlight nw,RHR taillight nw,one remote key taped up but works						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1	•	
Road Conditions During Test Drive: Dry						Central locking	~		
,						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
	d by: Janine Bell								
Inspecte	Date: 24 Apr 20	24							
I have read	and understood th	is condition c	uide. Name:			Signature:			