

Report ID: 25,700,845 Version: 1 18 Apr 2024 Created:

Make: Nissan M	Nodel:	Navara	Body Style:	Utility			Pass	Fail	N/A
	Registration: GBJ536 Reg Expiry: 08 Jul 2024		Eng	Engine					
	Odometer: 297,247 Kms Good No: 25700845			Oil level					
VIN: MNTVCGD40A000223 N	Vext Service:		Service Histor	y:	Sn	noke & fumes	~		
				-	Pe	erformance	~		
Note: This report is not a warranty		6	Danta hava nat	harry discovered and an	-	pise	~		
This report is a guide only. Considera diagnostic testing undertaken. The ve	hicle has beer	n driven up to 50km/h	from cold. The	Vendor recommends		ling System	•		
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					Coolant condition				
	_					erformance	~		
Key: SSC P SSC	-0	S SC S W		S SC		diator / Hoses (visual)	~		
S = scratch	0			XXX		nsmission	•		
D = dent			The	S SC R		peration	~		
			10	JHIH	· - ·	Dise	~		
PT = paint defect C = crack	- 1		+	S S		utch	~		
P = pin dent						/ joints	~		
* = decals S SC W PIP			AL.	S SC		heel bearings	~		
SC = stone chips					Brakes				
W = significant scuffs S SC S SC S SC S SC S SC					_	erformance	~		
	Note: com					and Brake	v v		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•	- <b>f t</b> we	
Front Bonnet needs attention. LH Rear Tail lamp faded.					Tyres (lowest observed tread depth of tyres)				-
Aftermarket Head Lights.						ft front		.6	mm
						ght front	4.7 mm		-
								.2	mm
Conditions During Body Inspection:					<u> </u>			mm	
Under Carriage & Under Bonnet Inspection Comments				· ·	Spare Yes				
		<u>In comments</u>				pension			
Oil leak from Clutch Slave Cylinder. Surface rust on exposed metal under body surface.					ispension performance	~			
						eering performance	~		
						lock absorbers	~		
						Conditioning / Heater			
Interior Comments					Operation 🖌				
Poor					Electrical / Accessories				
Seats						ead lights	~		
Carpets Poor (Missing	g)				Ta	il lights		~	
						dicators	~		
Panels Poor	Poor			ashboard warning lights	~				
Dashboard Poor	oor				ipers (front & rear)	~			
						indow winder FL	~		
					W	indow winder FR	~		
General Comments				W	indow winder RL	~			
Gear Boot Centre Console missing trim. Steering wheel out of alignment.				W	indow winder RR	~			
Rh Rear Park lamp Not Working.					Re	ear view mirrors	~		
					Ra	idio (basic test only)	~		
					C	D (basic test only)	~		
					Nu	umber of keys	1		
					entral locking	>			
	<b></b>	•			Re	emote locking	>		
Engine Timing Mechanism: Timing Chain					Sa	t. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						eversing camera		~	
			11113.		Re	eversing camera			
Inspected by: Super Cheap			1113.		Re	Date: 17 Apr 202		•	

I have read and understood this condition guide.

Name: .....

Signature: .....