

Report ID: 25,709,213 Version: 1 24 Apr 2024 Created:

Make:	Honda	Model:	Inspire	Body Style:	Sedan] [Pass	Fail	N/A
Year:	2005	Registration:	MCG330	Reg Expiry:	24 Jul 2024	Engine			1
WoF Expiry:	25 Jan 2025	Odometer:	182,204 Kms	Good No:	25709213	Oil level	~		
VIN:	7AT08G0TX17103455	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	nical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	SC W	-0	SC S SC			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	C SC			715	HIL	Operation	~		
PT = paint def				$\left(\left \right\rangle \right)$		Noise	~		
C = crack				$+ \mathbf{\nabla}$		Clutch			~
P = pin dent	HIG				7414	CV joints	~		
* = decals	sc 916			The	AIR	Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs W		SC		SD	Performance	~		
Darkulara		Note: som	ne defects & blemishes	s may not be disp	blayed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyre			
						Left front 6.7 m			
						Right front		., .5	mm
						Left rear		.5 .1	mm
Conditions During Pody Inspection, Day						Right rear			mm
Conditions During Body Inspection: Dry						Spare	6.2 mm Yes		
Under Ca	rriage & Under Bor	nnet Inspectio	on Comments			Suspension			
	ody inspection	•				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories	•		
Seats	Good					Head lights	~		
Jeats						Tail lights	~		
Carpets	Good						~		<u> </u>
Panels	wear					Dashboard warning lights	~		<u> </u>
						Wipers (front & rear)	~		├──
Dashboa	ard cracked st	ereo screen, wea	r steering wheel			Window winder FL	~		
	I					Window winder FR	~		<u> </u>
General Comments						Window winder RL	~		<u> </u>
						Window winder RR	~		
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		<u> </u>
						Number of keys	2		L
Road Conditions During Test Drive: Dry						Central locking	2 V		
Koad Con	autions During Tes	u Drive:	Dry			Remote locking	-	~	<u> </u>
Engine Ti	ming Mechanism:	Cambelt	t			Sat. Nav. (basic test only)		-	~
-	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
Inspecte	d by: Melissa Wilson					Date: 24 Apr 20	24		

I have read and understood this condition guide.

Name: