

Report ID: 25,710,180 Version: 3 08 May 2024 Created:

Make:	BMW	Model:	5251	Body Style:	Wagon		Pass	Fail	N/A
Year:	2006	Registration:		Reg Expiry:	11 Jul 2024	Engine	1	I	
WoF Expiry:		Odometer:	143,979 Kms	Good No:	25710180	Oil level	~		
VIN:	WBANL52040CF36892	Next Service:		Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:		-0	P P	-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			TIN	BIL S	Operation	~		
R = rust PT = paint def				$\int$	JHIH	Noise	~		
C = crack					SC	Clutch			~
P = pin dent					세비	CV joints			~
* = decals	ssc 916			- NL		Wheel bearings	~		
SC = stone chips						Brakes	•		
W = significant scuffs S W S P S P W						Performance		~	
		Note: som	he defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~	•	
Body Insp	pection Comments	10000.3011	le delects & blemisnes	inay not be disp	ayed in the diagram		•	ofture	) )
					Tyres (lowest observed tread depth of tyres)				
						Left front		.0	mm
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Body Inspection:									mm
Under Carriage & Under Bonnet Inspection Comments						Spare N/A			
		inet inspectic	in comments			Suspension			
Engine oil le	EdKS					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		
Interior Comments						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	1001					Head lights	~		
Carpets	Poor					Tail lights	~		
						Indicators	~		
Panels	Poor					Dashboard warning lights	~		
Dashboa	rd Poor					Wipers (front & rear)	~		
						Window winder FL	~		
	_					Window winder FR	~		
	<u>Comments</u>					Window winder RL	~		
Door remote not working Radio no volume control					Window winder RR	~			
Interior hood lining and A pillar trim sagging					Rear view mirrors	~			
Remedy bra Sunroof no	ake shudder t working					Radio (basic test only)		~	
	- J					CD (basic test only)		~	
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking		~	
			·			Remote locking		~	
						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
							1	1	·
Inspected by: Lukin Koveskali Date: 20 Apr 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....