

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or

diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.		Cooling System			
	ction phor to purchase and this can be analiged for an additional charge.	Coolant condition	~		
Kana [Performance	<		
Key:	Radiator / Hoses (visual)	~			
D = dent R = rust SC W		Transmission			
		Operation	~		
PT = paint defect		Noise	~		
C = crack P = pin dent * = decels		Clutch			~
		CV joints	~		
* = decals SC = stone chips		Wheel bearings	~		
W = significant scuffs		Brakes			
S		Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram		Hand Brake	~		
minor windscreen stone chips		Tyres (lowest observed tread depth of tyres)			
		Left front	2.	0	mm
		Right front	2.	0	mm
		Left rear	6.	0	mm
Conditions During Body Inspection: Dry		Right rear	5.0		mm
		Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments		Suspension			
All wheel drive		Suspension performance	~		
		Steering performance	~		
		Shock absorbers	~		
		Air Conditioning / Heater			
		Operation	~		
Interior Comments		Electrical / Accessories			
Seats	Good	Head lights	<		
Correcto	Good	Tail lights	<		
Carpets		Indicators	<		
Panels	Good	Dashboard warning lights	<		
	Good	Wipers (front & rear)	<		
Dashboard		Window winder FL	~		
		Window winder FR	~		
<u>General Comments</u>		Window winder RL	<		
		Window winder RR	~		
		Rear view mirrors	~		
		Radio (basic test only)	~		
		CD (basic test only)			~
		Number of keys	1		
Road Conditions During Test Drive: Dry		Central locking	~		
		Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:		Sat. Nav. (basic test only)	~		
		Reversing camera	~		
Inspected by: Rowan Fey Date: 24 Apr 2024					

I have read and understood this condition guide.

Name:

Signature:

Report ID: 25,714,884 Version: 2 02 May 2024 Created:

Pass

V

V

V

V

Engine

Oil level

Noise

Smoke & fumes

Performance

Fail

N/A