

Report ID: 25,714,953

Pass

1

V

/

V

1

Tyres (lowest observed tread depth of tyres)

Version: 2

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Left rear

Right rear

Suspension

Operation

Head lights Tail lights Indicators

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL

Window winder RR

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. Nav. (basic test only)

Suspension performance Steering performance

Spare

Right front

Coolant condition Performance

Radiator / Hoses (visual)

Created: 24 Apr 2024

Fail

N/A

mm

mm

mm

 mm

4.0

4.0

5.0

5.0

1

/

/

/

1

1

1

~


~

Yes

Make: Holden Model: Commodore **Body Style:** Sedan Year: 1993 Registration: HSVO53 **Reg Expiry:** 28 Jul 2024 WoF Expiry: **Odometer:** 04 Oct 2024 150,776 Kms **Good No:** 25714953 VIN: 6H8VRK19URL675416 Next Service: 155,000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Horn is not working. Minor oil leak.

*** THIS HOLDEN COMMODORE CLUBSPORT HAS BEEN RE-REGISTERED IN THE PAST DUE TO ACCIDENT DAMAGE, THERE IS A FLAG REGISTERED WITH NZTA TO SAY THIS ***

Road Conditions During Test Drive: Dry

I have read and understood this condition guide.

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

24 Apr 2024 Inspected by: Lewis Dolamore Date:

Name

:	 Signature:	