

Note: This report is not a warranty	Performance	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been disma	antled or Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor reco a full mechanical inspection prior to purchase and this can be arranged for an additional charge.	ommends Cooling System	Cooling System		
a fuir meenaniear inspection prior to parenase and this can be arranged for an additional charge.	Coolant condition	~		
	Performance	~		
Key: S = scratch	Radiator / Hoses (vis	sual) 🖌		
	Transmission			
	S Operation	~		
PT = paint defect	Noise	~		
C = crack	Clutch	~		
P = pin dent	CV joints		~	
	P Wheel bearings	~		
SC = stone chips	Brakes		I	
W = significant scuffs S P P P S	Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the	e diagram Hand Brake	~		
Left front bumper corner misaligned	Tyres (lowest observe	Tyres (lowest observed tread depth of tyres)		
Windscreen chips	Left front	3	; mm	
	Right front	3	s mm	
	Left rear	6	; mm	
Conditions During Body Inspection:	Right rear	6	; mm	
	Spare		Yes	
Under Carriage & Under Bonnet Inspection Comments	Suspension			
Left front tyres worn on outer edge	Suspension perform	nance 🖌		
Engine oil leaks	Steering performan	ce 🖌		
	Shock absorbers	~		
	Air Conditioning / H	eater		
	Operation	~		
Interior Comments	Electrical / Accessori	es		
Seats Good	Head lights	~		
Good	Tail lights	· ·		
Carpets	Indicators	· ·		
Panels Good	Dashboard warning	lights 🖌		
	Wipers (front & rear	5		
Dashboard Good	Window winder FL	· · ·		
	Window winder FR	· ·		
General Comments	Window winder RL	· ·		
	Window winder RR	· ·		
	Rear view mirrors	· ·		
	Radio (basic test on			
	CD (basic test only)	· · ·		
	Number of keys	1		
Pood Conditions During Test Driver	Central locking			
Road Conditions During Test Drive: Dry	Remote locking		<ul> <li>✓</li> </ul>	
Engine Timing Mechanism: Timing Chain	Sat. Nav. (basic test	only)	v v	
Evidence of Cam Belt Replacement: Not Applicable Kms:	Reversing camera	Jilly/	-	
			<ul> <li>✓</li> </ul>	
Inspected by: Lukin Koveskali Date: 30 Apr 2024				

I have read and understood this condition guide.

Name: .....

Report ID: 25,719,744 Version: 1 30 Apr 2024 Created:

Pass

r

V

Fail

N/A