

Basic Vehicle Condition Guide

Report ID: 25,720,751

Pass

1

~

/

V

1

Tyres (lowest observed tread depth of tyres)

Version: 1

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Right front

Left rear

Right rear

Suspension

Operation

Head lights Tail lights Indicators

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. Nav. (basic test only)

Suspension performance Steering performance

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 30 Apr 2024

Fail

N/A

1

mm

mm

mm

 mm

2.8

2.8

2.8

3.4

1

/

/

/

1

2

1

~


~

Yes

Make: Subaru Model: Outback **Body Style:** Wagon Year: 2005 Registration: **KER197 Reg Expiry:** 16 Nov 2024 WoF Expiry: **Odometer:** 05 Feb 2025 151,660 Kms **Good No:** 25720751 VIN: 7AT0GF16X16022377 **Next Service:** 160000kms **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chips, and small crack in windscreen Multiple pin dents in bonnet

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Engine oil leaks

Interior Comments		
Seats	Average	
Carpets	Average	
Panels	Average	
Dashboard	Average	

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement:

Lindsay Malpas

I have read and understood this condition guide.

Kms:	Reversing camera	
	Date: 29 Apr 2024	_
Name:	Signature:	