

## **Basic Condition Guide**

Report ID:	25,867,737	Version:	1
Created:	21 Nov 2025		

	_							
Make:	Hyundai	Model:	Kona			Requires	NI/A	
Body Style:	SUV	Year:	2022	Engine	OK	Attention	N/A	
Rego No.:	PNR899	Rego Expiry:	19 Jan 2026	Oil level		<u> </u>	V	
WoF Expiry:	20 Oct 2026	Odometer:	23,577 Kms	Smoke & fumes	V			
Good No.:	25867737	VIN:	KMHK281GUNU164486	Engine performance	1		-	
Next Service:	40,000 Kms	Service History:	Yes	Noise	V		<del>                                     </del>	
lote: This report is r	not a warranty		Coolant condition	1				
lagnostic testing unc	only. Consideration is made dertaken. The vehicle has b	een driven up to 50km/ł	Cooling performance	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \				
ull mechanical inspe	ction prior to purchase and	d this can be arranged fo	Radiator / Hoses (visual)	1				
(ey	5			Transmission		<u> </u>		
	= Rust $C = C$ = Paint defect $P = P$		· • • • • • • • • • • • • • • • • • • •	Operation	· /	<u> </u>		
- DCIIC 11			Noise	1				
			Clutch	+		1		
			CV joints	· /		<u> </u>		
	$(0)_{\mathbb{Z}}$		S	Wheel bearings	1			
				Brakes		<u> </u>	<u> </u>	
M	AMI			Performance	V	<u> </u>		
		-		Hand brake	1			
	0 1					tures)		
$$ $\theta$				Tyres (lowest observed tread depth of tyres)  Left front  6.0 mn				
		+	Right front		3.0 mn			
				Left rear	5.0 mm			
	W			Right rear	5.0 mn			
latar sama dafasts a	nd blemishes may not be	displayed in the diagra		Spare	N/A			
Body Inspectio	·	displayed in the diagra	III	Suspension				
body inspectio	an comments			Suspension performance	V			
				Steering performance	1			
				Shock absorbers	1			
Conditions Duri	ng Body Inspection		Dry	Air Conditioning / Heater	-			
	and Under Bonnet	Inspection Comm	-	Operation 🗸				
0.1.0.0.1.0.0.0.0.0.0.0.0.0.0.0.0.0.0.0				Electrical / Accessories				
				Head lights	V			
				Tail lights	· /			
Interior Comm	ents			Indicators	1			
Seats:	Average			Dashboard warning lights	· /			
Carpets:	Average			Wipers (front & rear)	1			
Panels:	Average			Window winder FL	1			
Dashboard:	Average			Window winder FR	1			
General Comm	_		Window winder RL	1				
State of Health -			Window winder RR	1				
Range at Full Ch	narge - 477Kms			Rear view mirrors	1			
				Radio (basic test only)	1			
Road Condition	s During Test Drive	Dry	CD (basic test only)	+ ·		1		
Engine Timing N		Unknown	Number of keys	2	1			
	n Belt Replacement	Yes	Central locking	- V				
Inspected by:	Greg Morgan		No Kms	Remote locking	1			
Published by:	Francois Kleyn		Sat. nav. (basic test only)	+		1		
Inspection Date:	-		Reversing camera	· /		Ť		
						1	1	

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE