


Make:	Holden	Model:	Colorado
Body Style:	Utility	Year:	2013
Rego No.:	HBS731	Rego Expiry:	15 Sep 2025
WoF Expiry:	28 Jan 2027	Odometer:	191,194 Kms
Good No.:	25917071	VIN:	MMU148FH0DH692979
Next Service:	6/3/25	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

Minor stone chips on windscreen.  
Holes in dash panels from items being removed.  
Rust on bonnet. Paint bubbles on bonnet

Conditions During Body Inspection	Dry
-----------------------------------	-----

**Under Carriage and Under Bonnet Inspection Comments**

Four wheel drive

**Interior Comments**

Seats:	Good
Carpets:	rip on drivers floor-Average
Panels:	Good
Dashboard:	hole in dashboard-Average

**General Comments**

Due for service since 6/3/25.  
Missing floor mats. Spare key damaged/broken

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Cambelt
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No
Inspected by:	Cameron Senior-Arnold
Published by:	Kendal Slight
Inspection Date:	10 Dec 2025

I have read and understood  
this condition guide:

NAME \_\_\_\_\_

Report ID:	25,917,071	Version:	3
Created:	29 Jan 2026		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front		8 mm	
Right front		5.8 mm	
Left rear		5.2 mm	
Right rear		5.7 mm	
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

SIGNATURE \_\_\_\_\_