

Report ID:	25,917,085	Version:	3
Created:	16 Dec 2025		

Make:	Mazda	Model:	Bt-50
Body Style:	Utility	Year:	2019
Rego No.:	MGA224	Rego Expiry:	30 Jun 2026
WoF Expiry:	25 Jul 2026	Odometer:	88,762 Kms
Good No.:	25917085	VIN:	MM0UR0YG100981048
Next Service:	95000	Service History:	Yes
liagnostic testing un	only. Consideration is made	een driven up to 50km/ł	arts have not been dismantled or n from cold. The Vendor recommends a or an additional charge.
Key			
	= Rust $C = C$ C = Paint defect $P = Pi$		
	- rame defect r = r	indent 5e=5tol	inc Criip3
		S	
	\alpha		
sc 6			
	M 11		
			sc
sc	R		
			(Q)
		P	
Note: some defects	and blemishes may not be	displayed in the diagra	ım
Body Inspecti	on Comments		
•	on windscreen Minor		
	s on windscreen repairs or replaceme	ents will be the resp	onsibility of the purchaser
Conditions Dur	ing Body Inspection		Dry
Under Carriag	e and Under Bonnet	Inspection Comm	ents
Four wheel drive	e		
Interior Comm	nents		
	Good		
Seats:			
Seats: Carpets:	Good		
	Good Good		
Carpets:			
Carpets: Panels: Dashboard: General Comm	Good Good nents		
Carpets: Panels: Dashboard:	Good Good nents		

		Requires	NI/A
Engine	OK	Attention	N/A
Oil level	/		1
Smoke & fumes	V		
Engine performance			
Noise	\(\tau \)		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	<i>J</i>		
Transmission			
Operation	V	l	
Noise	~		
Clutch			
CV joints	V		<u> </u>
Wheel bearings	· ·		
Brakes			l
Performance	/		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tvres)	l
Left front	Сригог		1.0 mm
Right front			1.2 mm
Left rear			3.3 mm
Right rear			9.4 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater		<u> </u>	
Operation	V		
Electrical / Accessories			
Head lights		V	
Tail lights	1		
Indicators	V		
Dashboard warning lights	V		
Wipers (front & rear)	\(\sigma \)		
Window winder FL	/		
Window winder FR	1		
Window winder RL	V		
Window winder RR	/		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)			~
Number of keys	1	•	
Central locking	1		
Remote locking	/		
Sat. nav. (basic test only)			
Reversing camera			/

Road Conditions During Test Drive		Dry		
Engine Timing Mechanism		Cambelt		
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	Cameron Senior-	Arnold		
Published by:	Kendal Slight			
Inspection Date:	10 Dec 2025			
	· ·		· ·	

have read and understood
this condition guide:

NAME	

SI	GN	JA.	ΓU	RF