


Report ID:	25,948,991	Version:	1
Created:	16 Apr 2026		

Make:	Mazda	Model:	CX-5
Body Style:	Wagon	Year:	2013
Rego No.:	QFT671	Rego Expiry:	01 Jan 2026
WoF Expiry:	02 Oct 2026	Odometer:	146,567 Kms
Good No.:	25948991	VIN:	7AT0C144X23120132
Next Service:	137,108 kms	Service History:	No

**Note: This report is not a warranty**  
 This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**  
 S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

### Body Inspection Comments

R tail light damage, interior panel missing parts parts, both front lower arm bushes split, L front tyre cracked,

Conditions During Body Inspection    Wet

### Under Carriage and Under Bonnet Inspection Comments

Service overdue, vibration when on reverse gear.

### Interior Comments

Seats:	Poor
Carpets:	Poor
Panels:	Average
Dashboard:	Average

### General Comments

Both front seat torn, driver door window not working, I stop not working, interior driver door panel torn, service light on, minor oil leak from turbo.

Road Conditions During Test Drive	Wet	
Engine Timing Mechanism	Timing Chain	
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No	Kms
Inspected by:	Marlon Espena	
Published by:	Marlon Espena	
Inspection Date:	16 Apr 2026	

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			5 mm
Right front			9 mm
Left rear			5 mm
Right rear			5 mm
Spare		N/A	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights		✓	
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_