


Make:	Honda	Model:	FIT Shuttle
Body Style:	Wagon	Year:	2013
Rego No.:	QPA292	Rego Expiry:	15 Jan 2026
WoF Expiry:	16 Apr 2026	Odometer:	113,824 Kms
Good No.:	25955257	VIN:	7AT08G2YX24118026
Next Service:	77,000 kms	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

Missing spare tool and jack, parcel tray missing,

Conditions During Body Inspection	Dry
-----------------------------------	-----

**Under Carriage and Under Bonnet Inspection Comments**
**Interior Comments**

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Good

**General Comments**

Driver body seal torn, r rear window not working, both wing mirror not folding, spanner light on ( hmmf), both rear tyre cracked, L front tyre worn, service due,

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No
Inspected by:	Marlon Espena
Published by:	Marlon Espena
Inspection Date:	22 Jan 2026

I have read and understood  
this condition guide:

NAME \_\_\_\_\_

Report ID:	25,955,257	Version:	1
Created:	22 Jan 2026		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level		✓	
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front		7 mm	
Right front		7 mm	
Left rear		5 mm	
Right rear		5 mm	
Spare	No		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			
Reversing camera	✓		

SIGNATURE \_\_\_\_\_