


•	Report ID:	25,960,013	Version:	2
	Created:	04 Nov 2025		

	Гъ				Doci	a Cana	dition Guide	пероппь	•
		JM		S _	Dasi	CONC	altion Guide	Created:	
Make:		Mitsubishi		Model:		Triton			_
Body Style:		Utility		Year:		2014		Engine	
Rego No.:		HJR870		Rego Ex	piry:	30 Sep	2026	Oil level	
WoF Expiry:	:	24 Sep 2026	3	Odomet	ter:	112,393	Kms	Smoke & f	- fı
Good No.:		25960013		VIN:		MMAJN	KB40ED001893	Engine pe	-
Next Service	e:	122000		Service I	History:	Yes		Noise	:1
Note: This repo		•		,				Coolant co	_ ი
diagnostic testir	ng un	dertaken. The vehi	cle ha b	een driven u	ıp to 50km/	h from cold.	ot been dismantled or The Vendor recommends a		-
	nspe	ction prior to purc	nase and	this can be	arranged	or an additio	nai cnarge.	Radiator /	′ ŀ
Key S = Scratch	R=	= Rust	C = C	rack	* = Deca	s	W = Significant scuffs	Transmis	si
D = Dent		= Paint defect			SC = Stor	-	vv signinearie seans	Operation	_ ۱
				+ 00	0 + 00		(0.000)	Noise	Ī
S SC	_		S	* SC	S * SC		S D SC	Clutch	Ī
						\bigcirc	SSC	CV joints	
			1 /~		_		/ 336	-	_



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Right and left kick boards gouged/orange lights fitted/aircon blow hot/hole in dash from rtrot

Conditions During Body Inspection

Under Carriage and Under Bonnet Inspection Comments

4x4/underbody covered in mud/minor underbody surface rust/

Interior Comments				
Seats:	Average			
Carpets:	Average			
Panels:	scratch marks			
Dashboard:	Average			

General Comments

Blows black smoke on heavy acceleration further investigation needed/shudder from rear further investigation needed

Road Condition	s During Test Drive	Dry		
Engine Timing N	Mechanism	Cambelt		
Evidence of Can	Evidence of Cam Belt Replacement		V No	Kms
Inspected by:	Uriah Pepene			
Published by:	Uriah Pepene			
Inspection Date:	04 Nov 2025			

	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes		'	
Engine performance	1		
Noise	~		
Coolant condition	V V		
Cooling performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch	~		
CV joints	V		
Wheel bearings	~		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			6 mm
Right front			6 mm
Left rear			5 mm
Right rear			5 mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	/		
Air Conditioning / Heater			
Operation		'	
Electrical / Accessories			
Head lights	~		
Tail lights	1		
Indicators	~		
Dashboard warning lights	1		
Wipers (front & rear)	•		
Window winder FL	•		
Window winder FR	•		
Window winder RL	1		
Window winder RR	•		
Rear view mirrors	•		
Radio (basic test only)	/		
CD (basic test only)	1		
Number of keys	1		
		I	
Central locking	•		
Central locking Remote locking	<i>'</i>		
	<i>V</i>		V

I have read and understood this condition guide:

NAME SIGNATURE