

# **Basic Condition Guide**

| • | Report ID: | 25,960,032  | Version: | 1 |
|---|------------|-------------|----------|---|
|   | Created:   | 04 Nov 2025 |          |   |


| Make:         | Toyota      | Model:           | Hilux             |
|---------------|-------------|------------------|-------------------|
| Body Style:   | Utility     | Year:            | 2014              |
| Rego No.:     | HSH112      | Rego Expiry:     | 30 Oct 2026       |
| WoF Expiry:   | 15 Dec 2025 | Odometer:        | 210,648 Kms       |
| Good No.:     | 25960032    | VIN:             | MR0FZ22G801087549 |
| Next Service: | 221820      | Service History: | No                |

# Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle habeen driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

### Kev

| ,           |                   |              |                  |                        |
|-------------|-------------------|--------------|------------------|------------------------|
| S = Scratch | R = Rust          | C = Crack    | * = Decals       | W = Significant scuffs |
| D = Dent    | PT = Paint defect | P = Pin dent | SC = Stone Chips |                        |



Note: some defects and blemishes may not be displayed in the diagram

# **Body Inspection Comments**

Glue from gps mount on windscreen/

| Conditions During Body Inspection | Dry |
|-----------------------------------|-----|
| Conditions During Body Inspection | Dry |

#### Under Carriage and Under Bonnet Inspection Comments

4x4/engine oil leak further investigation needed/minor underbody surface rust/

| Interior Comments |                                  |  |
|-------------------|----------------------------------|--|
| Seats:            | seat base pads stained           |  |
| Carpets:          | Average                          |  |
| Panels:           | scratch marks                    |  |
| Dashboard:        | holes from aftermarket switches/ |  |

# **General Comments**

| Road Conditions During Test Drive |              | Dry          |    |             |
|-----------------------------------|--------------|--------------|----|-------------|
| Engine Timing Mechanism           |              | Cambelt      |    |             |
| Evidence of Cam Belt Replacement  |              | <b>✓</b> Yes | No | 150,774 Kms |
| Inspected by:                     | Uriah Pepene |              |    |             |
| Published by: Uriah Pepene        |              |              |    |             |
| Inspection Date:                  | 04 Nov 2025  |              |    |             |

|                                | ОК          | Requires<br>Attention | N/A    |
|--------------------------------|-------------|-----------------------|--------|
| Engine                         |             |                       |        |
| Oil level                      | <b>/</b>    |                       |        |
| Smoke & fumes                  | <b>/</b>    |                       |        |
| Engine performance             | <b>/</b>    |                       |        |
| Noise                          | V<br>V<br>V |                       |        |
| Coolant condition              | <b>/</b>    |                       |        |
| Cooling performance            | <b>/</b>    |                       |        |
| Radiator / Hoses (visual)      | <b>/</b>    |                       |        |
| Transmission                   |             |                       |        |
| Operation                      | <b>✓</b>    |                       |        |
| Noise                          | <b>/</b>    |                       |        |
| Clutch                         |             |                       | 1      |
| CV joints                      | <b>/</b>    |                       |        |
| Wheel bearings                 | /           |                       |        |
| Brakes                         |             |                       |        |
| Performance                    | <b>✓</b>    |                       |        |
| Hand brake                     | /           |                       |        |
| Tyres (lowest observed tread d | epth of     | tyres)                |        |
| Left front                     |             | <u> </u>              | 6 mm   |
| Right front                    |             | (                     | 6.6 mm |
| Left rear                      |             |                       | 6 mm   |
| Right rear                     |             |                       | 6 mm   |
| Spare                          | Yes         |                       |        |
| Suspension                     |             |                       |        |
| Suspension performance         | <b>✓</b>    |                       |        |
| Steering performance           | <b>/</b>    |                       |        |
| Shock absorbers                | <b>/</b>    |                       |        |
| Air Conditioning / Heater      |             |                       | •      |
| Operation                      | <b>✓</b>    |                       |        |
| Electrical / Accessories       |             |                       |        |
| Head lights                    | <b>✓</b>    |                       |        |
| Tail lights                    | <b>✓</b>    |                       |        |
| Indicators                     | <b>V</b>    |                       |        |
| Dashboard warning lights       | <b>✓</b>    |                       |        |
| Wipers (front & rear)          | <b>/</b>    |                       |        |
| Window winder FL               | ~           |                       |        |
| Window winder FR               | <b>✓</b>    |                       |        |
| Window winder RL               | <b>✓</b>    |                       |        |
| Window winder RR               | <b>✓</b>    |                       |        |
| Rear view mirrors              | <b>✓</b>    |                       |        |
| Radio (basic test only)        | <b>✓</b>    |                       |        |
| CD (basic test only)           | <b>✓</b>    |                       |        |
| Number of keys                 | 2           |                       |        |
| Central locking                | <b>/</b>    |                       |        |
| Remote locking                 | <b>/</b>    |                       |        |
| Sat. nav. (basic test only)    |             |                       | ~      |
| Reversing camera               | <b>✓</b>    |                       |        |
|                                |             |                       |        |

I have read and understood this condition guide: