

Report ID:	25,960,406	Version:	2
Created:	26 Nov 2025		

		Requires	
	OK	Attention	N/A
Engine		<u> </u>	
Oil level	/		
Smoke & fumes	/		
Engine performance	/		
Noise	~		
Coolant condition	\(\times \) \(\t		
Cooling performance	/		
Radiator / Hoses (visual)			
Transmission	1		
Operation	/		
Noise	~		
Clutch			/
CV joints			/
Wheel bearings	'		
Brakes			
Performance	1		
Hand brake	'		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		6	6.5 mm
Right front		6	6.5 mm
Left rear		6	6.5 mm
Right rear		6	3.5 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	•		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories			
Head lights	~		
Tail lights	1		
Indicators	V		
Dashboard warning lights	/		
Wipers (front & rear)	~		
Window winder FL	1		
Window winder FR	1		
Window winder RL	1		
Window winder RR	1		
Rear view mirrors	1	1	
Radio (basic test only)	1		
CD (basic test only)		Ì	/
Number of keys	3		<u> </u>
Central locking	1	1	
Remote locking	/		
Sat. nav. (basic test only)			/
Reversing camera	1		

Good Seats: Good Carpets: Good Panels: Dashboard: Good **General Comments**

Road Condition	s During Test Drive	Wet
Engine Timing N	Mechanism	Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Xinghui Lin	
Published by:	Kenneth Mak	
Inspection Date:	14 Nov 2025	

I have read and understood
this condition auide:

NAME			