

Basic Condition Guide

Report ID: 25,961,083		Version:	1
Created:	03 Dec 2025		

	omei	S Das		Created:
Make:	Nissan	Model:	X-Trail	
Body Style:	SUV	Year:	2021	Engine
Rego No.:	o.: NTP954 Rego Expiry: 21 Jan 2026		Oil level	
WoF Expiry:	21 Oct 2026	Odometer:	85,669 Kms	Smoke & fur
Good No.:	25961083	VIN:	JN1JBAT32A0061749	Engine perfe
Next Service:	92,000 Kms	Service History:	Yes	Noise
Note: This report	is not a warranty			Coolant con
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a				Cooling per
full mechanical ins	pection prior to purchase an	d this can be arranged	for an additional charge.	Radiator / H
Key				Transmission
	R = Rust $C = CPT = Paint defect$ $P = P$		als W = Significant scuffs one Chips	Operation
	ri – railit delect r – r		опе спірз	Noise
S		w sc	SC	Clutch
	\sim		(\bigcirc)	CV joints Wheel beari
SC (<u> </u>		
	110		HIV	Brakes
	$\{\ \ \geq \ \ $		R SC	Performanc
				Hand brake
sc				Tyres (lowes
	The Contract of the Contract o		W	Left front
				Right front
S		S D		Left rear
				Right rear
	s and blemishes may not be	e displayed in the diagr	ram	Spare
Body Inspec	tion Comments			Suspension
				Suspension
				Steering per
				Shock absor
	uring Body Inspection		Dry	Air Condition
	ge and Under Bonnet		ments	Operation
Engine Oil See	epage, Further Investig	ation Required		Electrical / I
				Head lights
				Tail lights
Interior Com	ments			Indicators
Seats:	Good			Dashboard
Carpets:	Good			Wipers (fron
Panels:	Average			Window wir
Dashboard:	Average			Window wir
General Com	nments			Window wir
				Window wir
				Rear view m

	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	/		
Engine performance	1		
Noise	\(\tau \)		
Coolant condition	1		
Cooling performance	•		
Radiator / Hoses (visual)	1		
Transmission		<u> </u>	
Operation	V		
Noise	/		
Clutch			1
CV joints	/		
Wheel bearings	1		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		, ,	6 mm
Right front			7 mm
Left rear			4 mm
Right rear			4.5 mm
Spare	Yes		
Suspension			
Suspension performance	1		
Steering performance	1		
Shock absorbers	<i>'</i>		
Air Conditioning / Heater			
Operation	/		Π
Electrical / Accessories			
Head lights	V	1	
Tail lights	~		<u> </u>
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)			
Window winder FL			
Window winder FR			
Window winder RL	1		
Window winder RR	V		<u> </u>
Rear view mirrors			
	<i>'</i>		
Radio (basic test only)	4		<u> </u>
CD (basic test only)	1		<u> </u>
Number of keys Control locking	· ·	1	Ι
Central locking	<i>'</i>		
Remote locking	.,		
Sat. nav. (basic test only)	.,		
Reversing camera			

have read and understood
this condition guide:

Road Conditions During Test Drive

Evidence of Cam Belt Replacement

Inspection Date: 03 Dec 2025

Jaden Jenkins

Jaden Jenkins

Engine Timing Mechanism

Inspected by:

Published by:

NA	ME	

Wet

Timing Chain

No

Yes

S	IGI	N A	TI	JR	F

Kms