

•	Report ID:	25,961,134	Version:	1
	Created:	01 Dec 2025		


	ОК	Requires Attention	N/A
Engine	<u> </u>	7 (CCC) (CC)	14//
Oil level	/		
Smoke & fumes	/		
Engine performance	✓		
Noise	/		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission			
Operation	/		
Noise	/		
Clutch			V
CV joints	✓		
Wheel bearings		•	
Brakes			
Performance	•		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front			4 mm
Right front			1 mm
Left rear			5 mm
Right rear			5 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	✓		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories			
Head lights	/		
Tail lights	/		
Indicators	✓		
Dashboard warning lights	/		
Wipers (front & rear)	•		
Window winder FL	•		
Window winder FR	•		
Window winder RL	/		
Window winder RR	✓		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)			
Number of keys	1		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)	/		
Reversing camera			

Make:	Toyota	Model:	Rav4
Body Style:	suv	Year:	2022
Rego No.:	PGT887	Rego Expiry:	30 Mar 2026
WoF Expiry:	10 Jan 2026	Odometer:	87,448 Kms
Good No.:	25961134	VIN:	JTMZ43FV50D124578
Next Service:	90411	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

key				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Crack in cva/fr tyre major inner edge wear tyre needs replacing/rear tyres inner edge

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

2wd/

Interior Comments		
Seats:	Average	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	

General Comments

Wheel bearing noise from front and minor wobble further investigation needed

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Uriah Pepene	
Published by:	Uriah Pepene	
Inspection Date:	01 Dec 2025	

I have read and understood
this condition guide:

NAME			