

е

Report ID:	25,961,168	Version:	3
Created:	15 Dec 2025		


		ОК	Requires Attention	N/A
	Engine			
	Oil level	/		
	Smoke & fumes	1		
	Engine performance	1		
	Noise	1		
	Coolant condition	1		
ds a	Cooling performance	1		
	Radiator / Hoses (visual)	1		
cuffs	Transmission			
.uiis	Operation	V	<u> </u>	
	Noise	1		
	Clutch			
_	CV joints	·		
	Wheel bearings	1		
	Brakes			
	Performance	· /	l	Π
	Hand brake	1		
			t	
	Tyres (lowest observed tread	depth of	· ·	- 0
	Left front			5.0 mm
	Right front			5.0 mm
	Left rear			5.0 mm
	Right rear	.,		5.0 mm
	Spare	Yes		
	Suspension		T	ı
	Suspension performance	/		
	Steering performance	/		
	Shock absorbers	/		
	Air Conditioning / Heater		T	
	Operation	/		
	Electrical / Accessories			
	Head lights	/		
	Tail lights	/		
	Indicators	/		
	Dashboard warning lights	/		
	Wipers (front & rear)	/		
	Window winder FL	'		
	Window winder FR	V		
	Window winder RL	1		
	Window winder RR	V		
	Rear view mirrors	1		
	Radio (basic test only)	1		
	CD (basic test only)	1		
	Number of keys	1	1	
 (ms	Central locking	1		
	Remote locking	1		
	Sat. nav. (basic test only)			1
	Reversing camera	1		
	neversing current			

UII	nuer	S Basi	c Condition Guid
Make:	Toyota	Model:	Yaris
Body Style:	Hatchback	Year:	2017
Rego No.:	KWQ227	Rego Expiry:	30 Jan 2026
WoF Expiry:	26 Dec 2026	Odometer:	137,012 Kms
Good No.:	25961168	VIN:	JTDKW3D330D59397
Next Service:	147,100 kms	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommend full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key * = DecalsW = Significant sci S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

Interior Comments

2wd/

interior commi	CHS
Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

General Comments

Road Conditions During Test Drive		Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		Yes No Kms	
Inspected by:	Uriah Pepene		
Published by:	Ajaykumar Muruganandam		
Inspection Date:	01 Dec 2025		

I have read and understood this condition guide:

NAME			

SIGNATURE