

Basic Condition Guide

Report ID:	25,961,548	Version:	1
Created:	09 Dec 2025		

Engine

Oil level
Smoke & fumes
Engine performance

Noise

Coolant condition

Cooling performance

Radiator / Hoses (visual)

Transmission
Operation
Noise
Clutch
CV joints

Wheel bearings

Tyres (lowest observed tread depth of tyres)

Brakes
Performance
Hand brake

Left front

Right front

Left rear

Right rear

Suspension

Suspension performance

Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights
Wipers (front & rear)

Window winder FL Window winder FR Window winder RL

Window winder RR

Radio (basic test only)
CD (basic test only)

Rear view mirrors

Number of keys

Central locking
Remote locking

Steering performance

Shock absorbers

Operation

Head lights
Tail lights

Indicators

Spare

ОК

1

1

N/A

1

1

J

J

1

1

1

1

1

Requires

Attention

N/A

5.5 mm


5.5 mm

6.9 mm

6 mm

Make:	Holden	Model:	Acadia
Body Style:	SUV	Year:	2019
Rego No.:	MLN174	Rego Expiry:	31 Aug 2026
WoF Expiry:	25 Apr 2026	Odometer:	83,226 Kms
Good No.:	25961548	VIN:	1GHFN4RS1KZ300517
Next Service:	87800	Service History:	No
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.			

Key				
S = Scratch	R = Rust	C = Crack	* = Decals	W = Significant scuffs
D = Dent	PT = Paint defect	P = Pin dent	SC = Stone Chips	
SSC		SPSC	S D SC	SSC



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Boot don't line up further investigation needed/no flat tyre kit/

Conditions During Body Inspection Dry	Under Carriage and Under Bonnet Inspection Comme	ents
	Conditions During Body Inspection	Dry

All wheel drive/engine oil leak further investigation needed/

Interior Comm	ents
Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average
General Comments	

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Uriah Pepene	
Published by: Uriah Pepene		
Inspection Date:	09 Dec 2025	

Sat. nav. (basic test only)	/		
Reversing camera	V		
SIGNATURE			
	Reversing camera	Reversing camera 🗸	Reversing camera

I have read and understood
this condition guide: