

Basic Condition Guide

Report ID:	25,961,792	Version:	1
Created:	27 Nov 2025		

	Toyota	Model:	Corolla
Body Style:	Hatchback	Year:	2021
Rego No.:	NQL658	Rego Expiry:	26 Jan 2026
WoF Expiry:	29 Jul 2026	Odometer:	79,365 Kms
Good No.:	25961792	VIN:	JTNK43BE003141264
Next Service:	81,000kms	Service History:	Yes
agnostic testing un Il mechanical inspo ey = Scratch R	only. Consideration is mad dertaken. The vehicle has ection prior to purchase a	been driven up to 50km/ and this can be arranged to the contract of the	
	and blemishes may not b	e displayed in the diagra	S
	D. I. I		Dny
Conditions			Dry
		t Inconstian Com	<u> </u>
	e and Under Bonne	t Inspection Comn	<u> </u>
		t Inspection Comn	<u> </u>
		t Inspection Comn	<u> </u>
Under Carriag	e and Under Bonne	t Inspection Comn	<u> </u>
Under Carriag	e and Under Bonne	t Inspection Comn	<u> </u>
Interior Comn	nents Good	t Inspection Comn	<u> </u>
Interior Comm Seats: Carpets:	nents Good Good	t Inspection Comn	<u> </u>
Under Carriag Interior Comm Seats: Carpets: Panels:	nents Good Good Good	t Inspection Comn	<u> </u>
Interior Comm Seats: Carpets: Panels: Dashboard:	nents Good Good Good Good	t Inspection Comn	<u> </u>
Interior Comm Seats: Carpets: Panels: Dashboard:	nents Good Good Good Good	t Inspection Comn	<u> </u>
Interior Comm Seats: Carpets: Panels: Dashboard:	nents Good Good Good Good	t Inspection Comn	<u> </u>
Under Carriag Interior Comm Seats:	nents Good Good Good Good	t Inspection Comn	<u> </u>
Interior Comm Seats: Carpets: Panels: Dashboard:	nents Good Good Good Good	t Inspection Comn	<u> </u>
Interior Comm Seats: Carpets: Panels: Dashboard: General Comm	nents Good Good Good Good	t Inspection Comm	<u> </u>
Interior Comm Seats: Carpets: Panels: Dashboard: General Comm	nents Good Good Good Good ments		<u> </u>
Interior Comm Seats: Carpets: Panels: Dashboard: General Comm	nents Good Good Good Good ments	Dry	· · ·

		Requires	
	OK	Attention	N/A
Engine			<u> </u>
Oil level	/		
Smoke & fumes	/		
Engine performance	✓		
Noise	V		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	/		
Transmission		ı	
Operation	<u>/</u>		
Noise			
Clutch			
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	<u>/</u>		
Hand brake	/		
Tyres (lowest observed tread de	epth of	tyres)	
Left front			5 mm
Right front			5.5 mm
Left rear			1.5 mm
Right rear			5 mm
Spare	Yes		
Suspension		T	
Suspension performance			
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater		T	
Operation	/		
Electrical / Accessories		1	
Head lights	/		
Tail lights	/		
Indicators	/		
Dashboard warning lights	V V		
Wipers (front & rear)			
Window winder FL	V V		
Window winder FR	•		
Window winder RL	/		
Window winder RR	/		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)			'
Number of keys	2		
Central locking	~		
Remote locking	1		
Sat. nav. (basic test only)	/		
Reversing camera	/		
Remote locking Sat. nav. (basic test only)	V		

I have read and understood this condition guide:

Inspection Date: 27 Nov 2025

Published by:

NAME

LukaAjitvan Woerden

SIGNATURE