

## **Basic Condition Guide**

| Report ID: | 25,961,904  | Version: | 1 |
|------------|-------------|----------|---|
| Created:   | 29 Nov 2025 |          |   |

|   | ntuer   |                           |  |   |          |                       |      |
|---|---|---------------------------|--|---|----------|-----------------------|------|
| Make:   | Dodge   | Model:                    | Caliber                                      |   | ОК       | Requires<br>Attention | N/A  |
| Body Style:   | Hatchback   | Year:                     | 2006   | Engine  | OK       | Attention             | IN/A |
| Rego No.:   | QNR962  | Rego Expiry:              | 21 Jun 2026                                  | Oil level                                     | · /      |                       |      |
| WoF Expiry:   | 27 May 2026   | Odometer:                 | 221,618 Kms                                  | Smoke & fumes                                 | 1        |                       |      |
| Good No.:   | 25961904  | VIN:                      | 1B3H348A57D196858                            | Engine performance                            | 1        |                       |      |
| Next Service:   | 230,476   | Service History:          | No   | Noise   | 1        |                       |      |
| lote: This report is  | ,   |                           | Coolant condition                            | 1   |          |                       |      |
| iagnostic testing un  | e only. Consideration is made<br>ndertaken. The vehicle has b<br>rection prior to purchase and  | Cooling performance       | 1  |   |          |                       |      |
| · ·   | - Cettori prior to parenase arr   | Radiator / Hoses (visual) | 1  |   |          |                       |      |
| <b>Yey</b><br>= Scratch R   | = Rust C = C  | Transmission              |  |   |          |                       |      |
|   | T = Paint defect P = | Operation                 | <b>/</b>                                     |   |          |                       |      |
|   |   | Noise                     | 1  |   |          |                       |      |
|   | S   | P                         | Clutch                                       | 1   |          |                       |      |
|   |   |                           | CV joints                                    | 1   |          |                       |      |
|   | MA OF   |                           | Wheel bearings                               | 1   |          |                       |      |
| $-\!\!\!-\!\!\!\!-\!$ |   |                           | Brakes                                       |   |          |                       |      |
|   | M 11  |                           |  | Performance                                   | <b>/</b> |                       |      |
|   |   | -                         |  | Hand brake                                    | 1        |                       |      |
| sc  | 18  |                           | Tyres (lowest observed tread depth of tyres) |   |          |                       |      |
|   |   |                           | Left front                                   |   |          | 7 m                   |      |
|   |   |                           | (Q)  | Right front                                   |          |                       | 7 m  |
|   |   |                           | Left rear                                    |   |          | 7 m                   |      |
| ][_   |   | P S                       | Right rear                                   |   |          | 7 m                   |      |
| lote: some defects  | and blemishes may not be  | displayed in the diagra   | ım   | Spare   | Yes      |                       |      |
| Body Inspecti   | on Comments   |                           | Suspension                                   |   |          |                       |      |
|   |   |                           |  | Suspension performance                        | /        |                       |      |
|   |   |                           |  | Steering performance                          | /        |                       |      |
|   |   |                           |  | Shock absorbers                               | V        |                       |      |
| Conditions Dur  | ring Body Inspection  |                           | Air Conditioning / Heater                    |   |          |                       |      |
| Under Carriag   | ge and Under Bonnet   | Inspection Comm           | Operation                                    | <b>'</b>                                      |          |                       |      |
|   |   | Electrical / Accessories  |  |   |          |                       |      |
|   |   |                           |  | Head lights                                   | <b>/</b> |                       |      |
|   |   |                           |  | Tail lights                                   | <b>/</b> |                       |      |
| Interior Comm   | nents   |                           |  | Indicators                                    | /        |                       |      |
| Seats:  | Good  |                           |  | Dashboard warning lights                      | /        |                       |      |
| Carpets:  | Good  |                           |  | Wipers (front & rear)                         | /        |                       |      |
| Panels:   | Good  | Window winder FL          | <b>'</b>                                     |   |          |                       |      |
| Dashboard:  | Good  | Window winder FR          | /  |   |          |                       |      |
| Canaval Canav   | ments   |                           | Window winder RL                             | /   |          |                       |      |
| General Comr  | ands to far   |                           | Window winder RR                             | /   |          |                       |      |
|   | erius to iai.   |                           |  |   |          |                       |      |
|   | erius to iai.   |                           |  | Rear view mirrors                             |          | /                     |      |
|   | enus to iai.  |                           |  | Rear view mirrors  Radio (basic test only)    | /        |                       |      |
| Right mirror exte   | ns During Test Drive  | Dry                       |  |   | V        |                       |      |
| General Comm<br>Right mirror external<br>Road Condition<br>Engine Timing  | ns During Test Drive  | Dry<br>Cambelt            |  | Radio (basic test only)                       | 1        |                       |      |
| Right mirror exte<br>Road Conditior<br>Engine Timing                      | ns During Test Drive  | -                         | No 221,547 Kms                               | Radio (basic test only)  CD (basic test only) | 1        |                       |      |

I have read and understood this condition guide:

Inspection Date: 29 Nov 2025

LukaAjitvan Woerden

Published by:

NAME \_\_\_\_

SIGNATURE

Sat. nav. (basic test only)

Reversing camera