

•	Report ID: 25,961,915		Version:	1
	Created:	01 Dec 2025		

	ОК	Requires Attention	N/A
Engine	<u> </u>	Accention	1471
Oil level	/		
Smoke & fumes	/		
Engine performance	/		
Noise	✓ ✓		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	V		
Transmission		1	
Operation	/		
Noise	/		
Clutch			~
CV joints	1		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		· ·	3 mm
Right front			4 mm
Left rear			4 mm
Right rear			5 mm
Spare			
Suspension			
Suspension performance	V		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater		1	
Operation	1		
Electrical / Accessories		•	
Head lights	/		
Tail lights	1		
Indicators	1		
Dashboard warning lights	1		
Wipers (front & rear)	1		
Window winder FL	✓ ✓		
Window winder FR	/	1	
Window winder RL	/		
Window winder RR	/		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)	/		
Number of keys	2		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)		1	~
Reversing camera	1	1	


Make:	MG	Model:	3
Body Style:	Hatchback	Year:	2021
Rego No.:	NWZ413	Rego Expiry:	25 Nov 2025
WoF Expiry:	13 Jan 2026	Odometer:	30,582 Kms
Good No.:	25961915	VIN:	LSJZ14U91MS072872
Next Service:	30000km	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

* = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Windscreen has crack in CVA.

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

Interior Comments	
Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

General Comments

Front Wheel Drive.

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Haden Brown	
Published by:	Haden Brown	
Inspection Date:	01 Dec 2025	

I have read and understood
this condition guide:

NAME			