

•	Report ID:	25,962,174	Version:	2
	Created:	11 Dec 2025		

U	ruer	S Basi	C Condition Guide	Created: 11 Dec 2025				
Make:	Honda	Model:	FIT		OK	Requires Attention	N/A	
Body Style:	Hatchback	Year:	2013	Engine	OK	Attention	13/73	
Rego No.:	PYW159	Rego Expiry:	31 Jul 2025	Oil level	V			
WoF Expiry:	11 Jul 2025	Odometer:	118,984 Kms	Smoke & fumes	1			
Good No.:	25962174	VIN:	7AT08G2YX23231863	Engine performance	1			
Next Service:	127,082kms	Service History:	No	Noise	1			
Note: This report is r	•			Coolant condition				
diagnostic testing und	only. Consideration is made dertaken. The vehicle has b	Cooling performance	1					
•	ction prior to purchase an	Radiator / Hoses (visual)	1					
Key S = Scratch R =	Dust C C	ivaels * Daga	ls W Cignificant souffs	Transmission	-			
	= Rust $C = C$ = Paint defect $P = P$			Operation	V			
				Noise	1			
P		SP	S	Clutch				
				CV joints	1			
	$(0)_{\mathbb{F}}$			Wheel bearings	1			
S SC				Brakes				
	Pr II			Performance	·			
		—		Hand brake	1			
SC	A			Tyres (lowest observed tread depth of tyres)				
\longrightarrow A				Left front	6 mm			
				Right front	6.5 mm			
				Left rear	6.5 mm			
	S	P	P	Right rear			7 mm	
Note: some defects a	nd blemishes may not be	displayed in the diagra	ım	Spare	N/A			
Body Inspection				Suspension				
Coolant overflow				Suspension performance	V			
Tire repair kit ins	stead of spare.			Steering performance	1			
				Shock absorbers	1			
Conditions Duri	ng Body Inspection		Dry	Air Conditioning / Heater				
Under Carriage	e and Under Bonnet	Inspection Comm	ents	Operation	/			
				Electrical / Accessories				
				Head lights	/			
				Tail lights	1			
Interior Comm	ents			Indicators	~			
Seats:	Good			Dashboard warning lights	~			
Carpets:	Good			Wipers (front & rear)	~			
Panels:	Good			Window winder FL	~			
Dashboard: Good				Window winder FR	~			
General Comm	nents	Window winder RL		/				
Vehicle dead at time of inspection.				Window winder RR	~			
Left mirror not retracting. L/R window not working.				Rear view mirrors		~		
	controls not working.			Radio (basic test only)	~			
Road Condition	s During Test Drive	Dry		CD (basic test only)			✓	
Engine Timing N	Mechanism	Timing Chain		Number of keys	1			

I have read and understood this condition guide:

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Inspection Date: 11 Dec 2025

LukaAjitvan Woerden

LukaAjitvan Woerden

NAME			

No

Kms

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

SIGNATURE			

1