

•	Report ID:	25,989,386	Version:	4
	Created:	27 Nov 2025		

	ОК	Requires Attention	N/A
Engine			
Oil level	1		
Smoke & fumes	~		
Engine performance	1		
Noise	V		
Coolant condition	1		
Cooling performance	~		
Radiator / Hoses (visual)	1		
Transmission			
Operation	~		
Noise	1		
Clutch			1
CV joints	1		
Wheel bearings	1		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front	<u> </u>		3.0 mm
Right front			3.5 mm
Left rear		5	5.0 mm
Right rear			5.0 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater			
Operation	1		
Electrical / Accessories			
Head lights	1		
Tail lights	1		
Indicators	1		
Dashboard warning lights	1		
Wipers (front & rear)	/		
Window winder FL	1		
Window winder FR	1		
Window winder RL	1		
Window winder RR	·		
Rear view mirrors	1		
Radio (basic test only)	<i>'</i>		
CD (basic test only)			
Number of keys	2	l .	
Central locking	_	1	
Remote locking	1		
Sat. nav. (basic test only)			
Reversing camera	/		<u> </u>
neversing carriera		<u> </u>	


Make:	Hyundai	Model:	Staria Load		
Body Style:	Van	Year:	2022		
Rego No.:	PGY546	Rego Expiry:	28 Feb 2026		
WoF Expiry:	07 Jul 2026	Odometer:	24,420 Kms		
Good No.:	25989386	VIN:	KMFYFX71MNU046734		
Next Service:	32900	Service History:	No		
N. d. This are the second of t					

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

* = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Left front tyre sidewall damage Has tyre change tools

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				

Front wheel drive

	Interior Comments		
Seats: torn driver seat, rest good			
Carpets: Good		Good	
Panels: Good		Good	
Dashboard: Good		Good	
	General Comments		

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Kaleb Chandler	
Published by:	Kendal Slight	
Inspection Date:	21 Oct 2025	

I hav	ve read	and	understood
thic	conditi	on a	uide.

NAME			

SI	GN	IA.	TU	RF