

Basic Condition Guida

•	Report ID:	25,989,522	Version:	5	
	Created:	03 Dec 2025			

Basic Condition Guide			Neportib. 23,369,322 Version. 3					
Basic Condition Guide				Created: 03 Dec 2025				
Make:	Toyota	Model:	Hilux			ОК	Requires	
Body Style:	Utility	Year:	2020	Engine			Attention	N/A
Rego No.:	MSD62	Rego Expiry:	12 Feb 2026	Oil level		V		
WoF Expiry:	06 Mar 2026	Odometer:	76,990 Kms	Smoke & fu	ımes	V		
Good No.:	25989522	VIN:	MR0JA3DB601591039	Engine per		V		
Next Service:	82000	Service History:	Yes	Noise	Torriance	1		
lote: This report is	not a warranty			Coolant co	ndition	V		
his report is a guide iagnostic testing u	e only. Consideration is mad ndertaken. The vehicle has	de for age and mileage. P been driven up to 50km/	Cooling pe		V			
ıll mechanical insp	ection prior to purchase a	nd this can be arranged	for an additional charge.		Hoses (visual)	V		
Cey				Transmiss				<u>l</u>
		Crack *= Deca			ion	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	Τ	
D = Dent P	T = Paint defect P = I	rin dent SC = Sto	one Chips	Operation		1		
				Noise		1		
				Clutch		-		
	(0)			CV joints		/		-
S D SC				Wheel bea	rings			
$\overline{}$	18			Brakes			<u> </u>	
		$\parallel \parallel \parallel \perp$		Performan		/		
				Hand brake		/		
SC				Tyres (lowest observed tread depth of tyres)				
				Left front		8.0 mi		
				Right front		8.0 mm		
				Left rear		6.5 mr		
s sc				Right rear			7	7.0 mm
lote: some defects	and blemishes may not b	e displayed in the diagr	am	Spare		Yes		
Body Inspecti	ion Comments			Suspensio	n			
Has tyre chang	e toolss			Suspension	n performance	/		
				Steering pe	erformance	V		
				Shock abso	orbers	V		
Conditions Du	ring Body Inspection		Dry	Air Condit	ioning / Heater	_		
Under Carria	ge and Under Bonne	t Inspection Comn	nents	Operation		/		
Rear wheel driv	/ee			Electrical /	'Accessories			
				Head light:	5	V		
				Tail lights		V		
Interior Comr	nents			Indicators		V		
Seats:	torn driver seat, r	est good		Dashboard	l warning lights	~		
Carpets:	Good			Wipers (fro	nt & rear)	V		
Panels:	Average			Window w	inder FL	V		
Dashboard: Poor			Window w	inder FR	V			
General Comments					inder RL			1
•	at Base pad torn.			Window w	inder RR			'
Minor Dent Front Bumper Bulbar Dashboard trim - Minor Scrapes, Scratches					mirrors	1		
	ı - Minor Scrapes, Sci ninor tear on material			Radio (basi	c test only)	1		
Road Conditions During Test Drive Dry				CD (basic t				1
Engine Timing Mechanism Timing Chain				Number of		2	1	
Evidence of Cam Belt Replacement Yes No Kms				Central loc		1		
1	Kalah Chandlar			22.76141700	9		+	

I have read and understood this condition guide:

Inspection Date: 23 Oct 2025

Inspected by:

Published by:

Kaleb Chandler

Kendal Slight

NAME			

SIGNATURE			

Remote locking

Reversing camera

Sat. nav. (basic test only)

•