

## **Basic Condition Guide**

| Report ID: | 25,989,816  | Version: | 3 |
|------------|-------------|----------|---|
| Created:   | 05 Dec 2025 |          |   |

| U                         | rner   | S Basi                    | c Condition Guide         | Created: 05 Dec 2025                         |          |           |          |  |
|---------------------------|--|---------------------------|---------------------------|--|----------|-----------|----------|--|
| Make:                     | Hyundai  | Model:                    | lload                     |  |          | Requires  |          |  |
| Body Style:               | Van  | Year:                     | 2019                      |  | OK       | Attention | N/A      |  |
| Rego No.: MJY24           |  | Rego Expiry:              | 12 Dec 2025               | Engine                                       |          |           |          |  |
| WoF Expiry:               | 23 Sep 2026  | Odometer:                 | 117,971 Kms               | Oil level                                    | <b>/</b> |           |          |  |
| Good No.:                 | 25989816   | VIN:                      | KMFWBX7KMLU095986         | Smoke & fumes                                | <b>/</b> |           |          |  |
| Next Service:             | 131000   | Service History:          | No                        | Engine performance                           | <b>/</b> |           |          |  |
| Note: This report is r    | not a warranty   | ,                         | Noise                     | <i>\</i>                                     |          |           |          |  |
| This report is a guide of | only. Consideration is made<br>dertaken. The vehicle has b | e for age and mileage. Pa | Coolant condition         | <i>V</i>                                     |          |           |          |  |
| full mechanical inspe     | ction prior to purchase and                                | d this can be arranged fo | Cooling performance       | 7  |          |           |          |  |
| Key                       |  |                           | Radiator / Hoses (visual) |  |          |           |          |  |
|                           | Rust C=C   |                           | Transmission              | · /  | l        |           |          |  |
| D = Dent PT               | = Paint defect $P = Pi$                                    | Operation                 | 1                         |  |          |           |          |  |
|                           |  | P S                       | C                         | Noise  | -        |           | <b>V</b> |  |
|                           |  |                           | Clutch                    | · /  |          |           |          |  |
|                           | $\sim$   |                           | $(\bigcirc)$              | CV joints Wheel bearings                     | V        |           |          |  |
| SSC                       |  | <u> </u>                  |                           | Brakes                                       |          |           |          |  |
| M                         |  |                           | AH                        | Performance                                  | V        |           |          |  |
| 1                         |  |                           | SC                        | Hand brake                                   | 1        |           |          |  |
| sc                        |  |                           |                           | Tyres (lowest observed tread depth of tyres) |          |           |          |  |
| <u> </u>                  | N SE   |                           |                           | Left front                                   | Першог   |           | 7.5 mm   |  |
|                           |  |                           |                           | Right front                                  |          |           | 7.5 mm   |  |
|                           |  | Left rear                 | 3.0 mm                    |  |          |           |          |  |
|                           |  | Right rear                | 4.5 mm                    |  |          |           |          |  |
| Note: some defects a      | nd blemishes may not be                                    | displayed in the diagra   | m                         | Spare  | Yes      |           |          |  |
| Body Inspectio            |  |                           |                           | Suspension                                   |          |           |          |  |
| Has tyre change           |  |                           |                           | Suspension performance                       | <b>V</b> |           |          |  |
| Left Side Filler P        | anel: Damaged / Rig  | ht side filler panel \$   | Side Panel: Cracked       | Steering performance                         | 1        |           |          |  |
|                           |  |                           |                           | Shock absorbers                              | ~        |           |          |  |
| Conditions Duri           | ng Body Inspection   |                           | Air Conditioning / Heater |  |          |           |          |  |
| Under Carriage            | and Under Bonnet   | Inspection Comm           | Operation                 | <b>'</b>                                     |          |           |          |  |
| Rear wheel drive          | ee   |                           |                           | Electrical / Accessories                     |          |           |          |  |
|                           |  |                           |                           | Head lights                                  | <b>/</b> |           |          |  |
|                           |  |                           |                           | Tail lights                                  | <b>/</b> |           |          |  |
| Interior Comm             | ents   | Indicators                | <b>/</b>                  |  |          |           |          |  |
| Seats:                    | Average  |                           |                           | Dashboard warning lights                     | <b>/</b> |           |          |  |
| Carpets:                  | Average  |                           |                           | Wipers (front & rear)                        | /        |           |          |  |
| Panels:                   | Average  | Window winder FL          | <b>'</b>                  |  |          |           |          |  |
| Dashboard:                | Average  |                           | Window winder FR          | <b>'</b>                                     |          |           |          |  |
| General Comm              | ents   |                           | Window winder RL          |  |          | •         |          |  |
|                           |  |                           |                           | Window winder RR                             |          |           | <b>'</b> |  |
|                           |  |                           |                           | Rear view mirrors                            | <b>/</b> |           |          |  |
|                           |  |                           |                           | Radio (basic test only)                      | ~        |           |          |  |
| Road Condition            | s During Test Drive  | CD (basic test only)      |                           |  | 1        |           |          |  |

Kaleb Chandler Inspected by: Published by: Kendal Slight Inspection Date: 01 Nov 2025

Timing Chain

No

Yes

SIGNATURE

Number of keys

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

Kms

2

1

1

Engine Timing Mechanism

Evidence of Cam Belt Replacement