

Report ID:	25,989,885	Version:	1	
Created:	03 Nov 2025			

N/A

T.		Doo:	a Candition Cuida	Report ID:	25,989,885	Ve	rsion:	1	
	urner	S Basi	c Condition Guide	Created:	03 Nov 2025				
Make:	Mazda	Model:	Bt-50			ОК	Requ Atten		
Body Style:	Utility	Year:	2019	Engine					
Rego No.:	QZT689	Rego Expiry:	30 Nov 2025	Oil level		·			
WoF Expiry:	WoF Expiry: 15 Jan 2026 Odometer: 171,243 Kms		Smoke & fu	ımes	_				
Good No.:	25989885	VIN:	MM0UR0YG100872860	Engine per	formance	1		\dashv	
Next Service:	Next Service: 178,000		Yes	Noise		1		\dashv	
Note: This report is	•	,		Coolant co	ndition	1		-+	
diagnostic testing u	ndertaken. The vehicle ha b	peen driven up to 50km/	Parts have not been dismantled or 'h from cold. The Vendor recommends a	Cooling pe		1		\dashv	
	ection prior to purchase an	d this can be arranged f	or an additional charge.		Hoses (visual)	1			
Key S = Scratch R	= Rust	Crack *= Deca	ls W = Significant scuffs	Transmiss	ion				
	T = Paint defect P = P			Operation		·	1	Т	
				Noise		1		\dashv	
SC	sc	S D	SS	Clutch				$\neg \uparrow$	
				CV joints		1		\neg	
					rings	1		\neg	
SC				Brakes		ı			
	M 11.			Performan	ce	1			
			sc	Hand brake	e	1			
SC				Tyres (lowest observed tread depth of tyres)					
				Left front		2			
			SW	Right front				3.	
				Left rear				4.	
	S	S D	SS	Right rear				4.	
Note: some defects	Note: some defects and blemishes may not be displayed in the diagram			Spare		Yes			
	on Comments			Suspensio	n				
Stone chip with	leas in the CVA tailo	ate side clips are r	usted on and require a hammer	Sucpension	nerformance	1			

Stone chip with legs in the CVA, tailgate side clips are rusted on and require a hammer to drop the tailgate,

Conditions During Body Inspection	Dry
Under Carriage and Under Bonnet Inspection Comm	ents

Interior Comm	ents
Seats:	stains
Carpets:	Good
Panels:	Good
Dashboard:	Good

General Comments

2WD,

Road Condition	s During Test Drive	Dry		
Engine Timing Mechanism		Timing Cha	in	
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	Jesse Roberts			
Published by:	Jesse Roberts			
Inspection Date:	03 Nov 2025			

Performance	'		
Hand brake	~		
Tyres (lowest observed tread	depth of t	yres)	•
Left front		:	2.2 m
Right front		;	3.8 m
Left rear		-	4.6 m
Right rear		•	4.8 m
Spare	Yes		
Suspension			
Suspension performance	V		
Steering performance	'		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	'		
Electrical / Accessories			
Head lights	'		
Tail lights	V V		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	/		
Window winder FL	'		
Window winder FR	'		
Window winder RL			1
Window winder RR			1
Rear view mirrors	'		
Radio (basic test only)	'		
CD (basic test only)	'		
Number of keys	1		
Central locking	V		
Remote locking	'		
Sat. nav. (basic test only)			1
Reversing camera			1

I have read and understood this condition guide:

NAME SIGNATURE