

## **Basic Condition Guide**

Report ID:	25,989,956	Version:	7
Created:	01 Dec 2025		

N/A

7.0 mm7.0 mm7.0 mm7.0 mm

				Created: 01 Dec 2025		
Make:	KIA	Model:	Seltos			Requires
Body Style:	SUV	Year:	2021	Fundan	OK	Attention
Rego No.:	NSF990	Rego Expiry:	23 Mar 2026	Engine		<u> </u>
WoF Expiry: 23 Sep 2026		Odometer:	59,112 Kms	Oil level	/	
Good No.:	25989956	VIN:	KNAEP81ATN7260339	Smoke & fumes	/	
Next Service:	8/5/26 or 75000kms	Service History:	No	Engine performance	/	
lote: This report is r	not a warranty	,	Noise	<b>/</b>		
his report is a guide o	only. Consideration is made	e for age and mileage. Pa	Coolant condition	<b>/</b>		
agnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a Il mechanical inspection prior to purchase and this can be arranged for an additional charge.				Cooling performance	/	
Кеу				Radiator / Hoses (visual)	<b>/</b>	
	= Rust $C = C$		Transmission			
D = Dent PT	= Paint defect $P = P$	in dent SC = Stor	ne Chips	Operation	/	
SC		Р	P	Noise	/	
$\overline{}$				Clutch		
	-00		W	CV joints	/	
sc d				Wheel bearings	<b>/</b>	
- H	A T			Brakes		
	MI = II			Performance	/	
				Hand brake	<b>/</b>	
SC	18 - IV			Tyres (lowest observed tread depth of tyres)		
J				Left front		
				Right front		
	$\angle$			Left rear		
P		P	P	Right rear		
lote: some defects a	and blemishes may not be	displayed in the diagra	m	Spare	Yes	
Body Inspection	on Comments			Suspension		
Has tyre change	tools			Suspension performance	V	
				Steering performance	V	
				Shock absorbers	V	
Conditions Duri	ing Body Inspection		Dry	Air Conditioning / Heater	_	•
Under Carriage	e and Under Bonnet	Inspection Comm	ents	Operation	<b>/</b>	
Front wheel drive	e			Electrical / Accessories		•
				Head lights	<b>/</b>	
				Tail lights	1	
Interior Comm	ents			Indicators	V	
Seats: Good				Dashboard warning lights	1	
Carpets:	Good			Wipers (front & rear)	1	
Panels:	Good			Window winder FL	1	
Dashboard: Good				Window winder FR	1	
General Comments				Window winder RL	1	
				Window winder RR	1	
				Rear view mirrors	1	
				Radio (basic test only)	1	
Road Condition	s Durina Test Drive	Dry		CD (basic test only)		
Road Conditions During Test Drive Dry  Engine Timing Mechanism Timing Chain				Number of keys	2	<u> </u>

I have read and understood this condition guide:

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Inspection Date: 06 Nov 2025

Kaleb Chandler

Kendal Slight

NAME			

Yes

No

Kms

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

SIGNATURE		

1