

Report ID: 25,990,191		Version:	2
Created:	24 Nov 2025		

O T	urner	S Basi	c Condition Guide
Make:	Polestar	Model:	Polestar 2
Body Style:	Hatchback	Year:	2022
Rego No.:	PPA425	Rego Expiry:	02 Feb 2026
WoF Expiry:	06 Nov 2026	Odometer:	133,659 Kms
Good No.:	25990191	VIN:	YSMVSEGA9PL128570
Next Service:	142000	Service History:	No
diagnostic testing ur	only. Consideration is made	een driven up to 50km/ł	arts have not been dismantled or n from cold. The Vendor recommends a or an additional charge.
Key			
•	= Rust C = C	rack *= Deca	ls W = Significant scuffs
D = Dent P	$\Gamma = Paint defect P = Pi$	in dent SC = Stor	ne Chips
		S	
		-	
	(M)-		S
SC		+	
SC A			
SC	18		
			(Q)
		S S	S
Note: some defects	and blemishes may not be	displayed in the diagra	ım
	on Comments		
Vehicle has a s	pare tyre as well as a	puncture repair kit	
Conditions Du	ring Body Inspection		Dry
	e and Under Bonnet	Inspection Comm	•
Front wheel driv		•	
Interior Comn	nents		
Seats:	Good		
Carpets:	Good		
Panels:	Good		
Dashboard:	Good		
General Com	nents		

Engine Oil level Smoke & fumes Engine performance Noise Coolant condition Cooling performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand brake Tyres (lowest observed tread delayed)	OK V V V V V v ppth of	Attention	N/A
Oil level Smoke & fumes Engine performance Noise Coolant condition Cooling performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand brake Tyres (lowest observed tread de	V V V V V V		<i>V</i>
Engine performance Noise Coolant condition Cooling performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand brake Tyres (lowest observed tread de	V V V V V V		<i>V</i>
Noise Coolant condition Cooling performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand brake Tyres (lowest observed tread de	V V V V V		<i>V</i>
Coolant condition Cooling performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand brake Tyres (lowest observed tread de	V V V V V		V
Cooling performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand brake Tyres (lowest observed tread de	V V V V		V
Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand brake Tyres (lowest observed tread de	\(\times \) \(\t		V
Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand brake Tyres (lowest observed tread de	\(\frac{1}{2} \)		<i>V</i>
Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand brake Tyres (lowest observed tread de	V V V		V
Noise Clutch CV joints Wheel bearings Brakes Performance Hand brake Tyres (lowest observed tread de	V V V		<i>V</i>
Clutch CV joints Wheel bearings Brakes Performance Hand brake Tyres (lowest observed tread de	V V V		✓
CV joints Wheel bearings Brakes Performance Hand brake Tyres (lowest observed tread de	V V		V
Wheel bearings Brakes Performance Hand brake Tyres (lowest observed tread de	V V		
Brakes Performance Hand brake Tyres (lowest observed tread de	<i>V</i>		
Performance Hand brake Tyres (lowest observed tread de	/		
Hand brake Tyres (lowest observed tread de	/		
Tyres (lowest observed tread de	•		
	pth of		
	•	tyres)	
		-	6.5 mm
Right front		6	6.5 mm
Left rear		4	I.0 mm
Right rear			3.5 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories			
Head lights	/		
Tail lights	/		
Indicators	/		
Dashboard warning lights	/		
Wipers (front & rear)	/		
Window winder FL	/		
Window winder FR	/		
Window winder RL	/		
Window winder RR	/		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)			/
Number of keys	1		
Central locking	/		
Remote locking	· ·		
Sat. nav. (basic test only)	~		
Reversing camera	~		

Road Condition	s During Test Drive	Dry		
Engine Timing I	Mechanism	Unknown		
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	Jaykib Collins			
Published by:	Kendal Slight			
Inspection Date:	12 Nov 2025			

I have read and understood	
this condition guide:	NAM

NAME	

SI	GN	IAT	ΓUI	RF