


| Report ID: | 25,990,428 | Version: | 2 |
|------------|-------------|----------|---|
| Created: | 20 Nov 2025 | | |

| Make: | Toyota | Model: | Corolla |
|---------------|-------------|------------------|-------------------|
| Body Style: | Hatchback | Year: | 2021 |
| Rego No.: | NUC94 | Rego Expiry: | 17 Apr 2026 |
| WoF Expiry: | 07 Nov 2025 | Odometer: | 92,512 Kms |
| Good No.: | 25990428 | VIN: | JTNK93BE503036771 |
| Next Service: | 92000 | Service History: | No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

| rey | | | | |
|-------------|-------------------|--------------|------------------|------------------------|
| S = Scratch | R = Rust | C = Crack | * = Decals | W = Significant scuffs |
| D = Dent | PT = Paint defect | P = Pin dent | SC = Stone Chips | |



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Has tyre change tools WOF expired Service overdue

| Conditions During Body Inspection | Dry | | |
|---|-----|--|--|
| Under Carriage and Under Bonnet Inspection Comments | | | |

Front wheel drivee

| | Interior Comments | | |
|------------------|-------------------|------|--|
| | Seats: | Good | |
| | Carpets: | Good | |
| | Panels: | Good | |
| | Dashboard: | Good | |
| General Comments | | | |

| Road Conditions During Test Drive | | Dry | | | |
|-----------------------------------|----------------|--------------|--|--|--|
| Engine Timing Mechanism | | Timing Chain | | | |
| Evidence of Cam Belt Replacement | | Yes No Kms | | | |
| Inspected by: | Kaleb Chandler | | | | |
| Published by: Jesse Roberts | | | | | |
| Inspection Date: | 16 Nov 2025 | | | | |

| I have read and understood |
|----------------------------|
| this condition guido: |

| NAME | | |
|------|--|--|

| | ОК | Requires Attention | N/A |
|--------------------------------|--------------|-----------------------|----------|
| Engine | | | |
| Oil level | ✓ | | |
| Smoke & fumes | ✓ | | |
| Engine performance | / | | |
| Noise | V V | | |
| Coolant condition | ✓ | | |
| Cooling performance | ✓ | | |
| Radiator / Hoses (visual) | / | | |
| Transmission | | | |
| Operation | / | | |
| Noise | / | | |
| Clutch | | | ' |
| CV joints | ✓ | | |
| Wheel bearings | / | | |
| Brakes | | | |
| Performance | ' | | |
| Hand brake | ✓ | | |
| Tyres (lowest observed tread d | epth of 1 | tyres) | |
| Left front | | 2 | 2.5 mm |
| Right front | | 2 | 2.5 mm |
| Left rear | | 3 | 3.5 mm |
| Right rear | | 3 | 3.5 mm |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | ✓ | | |
| Steering performance | ✓ | | |
| Shock absorbers | / | | |
| Air Conditioning / Heater | | | |
| Operation | ✓ | | |
| Electrical / Accessories | | | |
| Head lights | ✓ | | |
| Tail lights | ✓ | | |
| Indicators | ✓ | | |
| Dashboard warning lights | \(\times \) | | |
| Wipers (front & rear) | | | |
| Window winder FL | / | | |
| Window winder FR | / | | |
| Window winder RL | ✓ | | |
| Window winder RR | ✓ | | |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | / | | |
| CD (basic test only) | | | |
| Number of keys | 1 | | |
| Central locking | ✓ | | |
| Remote locking | ✓ | | |
| Sat. nav. (basic test only) | ✓ | | |
| Reversing camera | ✓ | | |

| SIGNATURE | | | |
|-----------|--|--|--|