

## **Basic Condition Guide**

'	Report ID:	25,990,561	Version:	1
	Created:	18 Nov 2025		

OK

Requires Attention

N/A

U	ntuel	S Basi	c Condition Guide	Created:				
Make:	Suzuki	Model:	Swift					
Body Style:	Hatchback	Year:	2022	Engine				
Rego No.:	NZF913	Rego Expiry:	16 Jan 2026	<b>Engine</b> Oil level				
WoF Expiry:	17 Mar 2026	Odometer:	50,123 Kms	Smoke &				
Good No.:	25990561	VIN:	JSAAZC83S00406019					
Next Service:	55000	Service History:	No	Engine po				
Note: This report is	not a warranty			Coolant				
			arts have not been dismantled or n from cold. The Vendor recommends a	Cooling				
full mechanical inspe	ection prior to purchase an	d this can be arranged f	or an additional charge.	Radiator				
Key				Transmis				
	= Rust $C = C$ $\Gamma$ = Paint defect $P = P$			Operation				
	I = I allit delect I = I		nie Criips	Noise				
<u>s</u>	W		S	Clutch				
				CV joints				
	$\mathcal{O}_{\mathcal{C}}$		$(\bigcirc)$	Wheel be				
S SC				Brakes				
M	ID I			Performa				
		]	R SC	Hand bra				
S D SC								
9133				Left front				
/			(Q)	Right from				
				Left rear				
			S	Right rea				
Note: some defects	and blemishes may not be	displayed in the diagra	ım	Spare				
Body Inspection	on Comments			Suspens				
Has tyre change				Suspensi				
Rear grab hand	lles not fitted			Steering				
				Shock ab				
Conditions Dur	ring Body Inspection		Dry	Air Cond				
Under Carriage and Under Bonnet Inspection Comments								
Front wheel drivee								
				Head ligh				
				Tail lights				
Interior Comm	nents			Indicators				

•			
V			
V			
1			
V			
V			
~			
Transmission			
V			
V			
	V		
V			
1			
	,		
V			
~			
depth of tyres	s)		
	6 mm		
	6 mm		
	5 mm		
	5.5 mm		
Yes			
V			
V			
V			
V			
V			
V			
1			
1			
1			
1			
1			
1			
	- ·		
2			
<b>/</b>	į.		
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			
<i>'</i>			
	Yes  Yes  V  V  V  V  V  V  V  V  V  V  V  V  V		

General Comments				
Road Conditions During Test Drive	Dry			
Engine Timing Mechanism	Timing Chain			
Evidence of Cam Belt Replacement	Yes No Kms			

rear grab handles missing, panels good.

has GPS wiring, otherwise ok

Evidence of Cam Belt Replacement Yes No Kms
Inspected by: Kaleb Chandler
Published by: Kaleb Chandler
Inspection Date: 18 Nov 2025

I have read and understood this condition guide:

Good

Good

Seats:

Carpets:

Panels:

Dashboard:

NAME \_\_\_\_

SIGNATURE