

## **Basic Condition Guide**

Report ID:	25,990,588	Version:	1
Created:	18 Nov 2025		

	Diffe			Created:	18 Nov 2025					
Make:	Hyundai	Model:	Santa FE				Requires			
Body Style:	SUV	Year:	2021	Engino			Attention	N/A		
Rego No.:	NWH566	Rego Expiry:	25 May 2026	Engine			<u> </u>			
WoF Expiry:	20 Dec 2025	Odometer:	104,953 Kms	Oil level		<i>/</i>				
Good No.:	25990588	VIN:	KMHS381HWMU406008	Smoke & fumes		<u> </u>				
				Engine performance						
Note: This report is			Noise /							
This report is a guide	only. Consideration is madertaken. The vehicle has	de for age and mileage								
	ection prior to purchase a		erformance							
Key				Radiator / Hoses (visual)						
		Crack *= De	cals W = Significant scuffs tone Chips	Transmiss			ı			
D = Dent P	$\Gamma = Paint defect  P = \Gamma$	Operation		/						
PT		SR PW	PT	Noise		<b>✓</b>				
		$\top$		Clutch				~		
			S	CV joints		<b>✓</b>				
S PT SC				Wheel bea	arings	/				
H				Brakes	Brakes					
			R SC	Performar	nce	<b>/</b>				
			No contraction of the contractio	Hand brak	e	<b>/</b>				
PT SC				Tyres (low	Tyres (lowest observed tread depth of tyres)					
				Left front		3.5 mm				
				Right fron	t	4 mm				
	$\sim$			Left rear		0 mm				
	<u>s</u>	S D P W	WSD	Right rear		2 mm				
Note: some defects	and blemishes may not b	e displayed in the diag	gram	Spare		Yes				
Body Inspecti	on Comments			Suspensi	on					
Has tyre change				Suspensio	n performance	<b>✓</b>				
LR tyre scallope	ed (WOF fail)			Steering p	erformance	•				
				Shock abs	orbers	<b>✓</b>				
Conditions Dur	ring Body Inspection		Dry	Air Condi	Air Conditioning / Heater					
Under Carriag	e and Under Bonne	t Inspection Com	ments	Operation 🗸						
All wheel drivee				Electrical	Electrical / Accessories					
				Head light	:S	/				
				Tail lights		/				
Interior Comm	nents			Indicators		<b>/</b>				
Seats:	Good			Dashboar	d warning lights	<b>/</b>				
Carpets:	Good			Wipers (fro	Wipers (front & rear)					
Panels:	Good				vinder FL	<b>/</b>				
Dashboard: reverse camera faulty					vinder FR	<b>/</b>				
General Comr	nents	Window v	vinder RL	<b>/</b>						
				Window v	vinder RR	<b>/</b>				
				Rear view		<b>/</b>				
					ic test only)	<b>/</b>				
Road Condition	ns During Test Drive	CD (basic				/				
Road Conditions During Test Drive Dry  Engine Timing Mechanism Timing Chain					Number of keys 2					
Evidence of Cam Belt Replacement Yes No Kms					king	<b>/</b>				
Inspected by:	Kaleb Chandler		(1113	Remote lo		~				
mopeeted by.	. talos orialidio	- ACTITOTE TO	19	_						

I have read and understood this condition guide:

Inspection Date: 18 Nov 2025

Published by:

NAME \_\_\_\_

Kaleb Chandler

SIGNATURE

Sat. nav. (basic test only)

Reversing camera