

•	Report ID: 25,990,831		Version:	1
	Created:	21 Nov 2025		

<b>-</b>	urner	Bas	ic Condition Guide	report ib:	25,990,651	Ve	131011.	
	onnei			Created:	21 Nov 2025			
Make:	Nissan	Model:	Skyline				Requires	
Body Style:	Sedan	Year:	2006			OK	Attention	N/A
Rego No.:	PEF837	Rego Expiry:	21 Jul 2025	Engine				1
WoF Expiry:	16 Jan 2026	Odometer:	136,495 Kms	Oil level		<i>V</i>		+
Good No.:	25990831	VIN:	7AT0DH12X21100195	Smoke & fu		V	-	-
Next Service:	140,000	Service History:	No	Engine per	formance	<b>V</b>		-
ote: This report is	,	,		Noise		<b>/</b>		₩
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or				Coolant co		<b>/</b>	-	┼
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.				erformance	<b>/</b>		-	
ey					Hoses (visual)	/		
= Scratch R	= Rust $C=C$	Crack *= Deca	ls W = Significant scuffs	Transmiss	ion		<u> </u>	_
= Dent P	T = Paint defect P = P	Pin dent SC = Sto	ne Chips	Operation		/		<u> </u>
S SC	sc	S S PT	SC S	Noise		/		<u> </u>
$\overline{}$	$\overline{}$	T		Clutch				\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
	\ \(\int_{\infty}\)		S SC	CV joints 🗸		/		
S PT SC		+		Wheel bearings		/		
5 11 30				Brakes				
			DT SC	Performan	ce	<b>/</b>		
PT SC				Hand brak	e	<b>/</b>		
S PT SC	18			Tyres (lowest observed tread depth of tyres)				
SC				Left front 5.7			5.7 m	
				Right front			6 n	
				Left rear				6 n
	SC S	S SC S PT SC	SC S	Right rear				6.4 m
Note: some defects and blemishes may not be displayed in the diagram				Spare Yes				
Body Inspect	ion Comments			Suspensio	n	_		
3onnet struts r	need replacing, crack i	in the windscreen,		Suspensio	n performance	/		
				Steering p	erformance	1		1
				Shock abso	orbers	1		1
Conditions During Body Inspection Dry			Air Conditioning / Heater					
	ge and Under Bonnet	t Inspection Comn	-	Operation		V		
Dil leaks,		•		Electrical / Accessories				
				Head light			·	
				Tail lights		1		1
Interior Comr	nents			Indicators		1	<u> </u>	1
Seats:	stains				I warning lights	1	<u> </u>	†
Carpets:	stains			Wipers (front & rear)			†	
Panels:	scratch marks		Window w		1		1	
Dashboard: cracked, left corner broken off,			Window w		1	<u> </u>	+	
General Com		J. D. O. O. I.		Window w		1		+
General Colli	ilicitis			vviiiuovv vv	IIIUCI IIL		-	₩

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Jesse Roberts	
Published by:	Jesse Roberts	
Inspection Date:	21 Nov 2025	

Engine tick, front park lights don't work, reversing camera is blurry, sat nav not for  $\ensuremath{\text{nz}}$ 

I have read and understood this condition guide:

roads,

NAME			

SIGNATURE		

1 1

1

1

1

1

Window winder RR

Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera